




PLASKOLITE



**TUFFAK® polycarbonate sheet**  
Fabrication guide / Technical manual

# Table of Contents

	Page
<b>Introduction</b>	3
<b>Typical Properties</b>	4
<b>TUFFAK Product Selection Guide</b>	5-6
<b>Chemical / Environmental Resistance</b>	7-13
<b>Cleaning Recommendations</b>	14-15
<b>Fabrication / Machining</b>	16-21
<b>Fabrication / Laminate &amp; Heavy Gauge Sheet</b>	22-25
<b>Thermoforming</b>	26-31
<b>Troubleshooting Guide</b>	32-40
<b>Brake Bending, Cold Forming, Annealing</b>	41-42
<b>Bonding Applications</b>	43-45
<b>Mechanical Fastening</b>	46-49
<b>Finishing</b>	50-52
<b>Glazing Guidelines</b>	53-58



**Contact Technical Service Group with additional questions:**

**800.628.5084**

**[plaskolite@plaskolite.com](mailto:plaskolite@plaskolite.com)**

# TUFFAK Sheet Typical Properties\*



Property	Test Method	Units	Values
<b>PHYSICAL</b>			
Specific Gravity	ASTM D 792	-	1.2
Refractive Index	ASTM D 542	-	1.586
Light Transmission, Clear @ 0.118"	ASTM D 1003	%	86
Light Transmission, I30 Gray @ 0.118"	ASTM D 1003	%	50
Light Transmission, K09 Bronze @ 0.118"	ASTM D 1003	%	50
Light Transmission, I35 Dark Gray @ 0.118"	ASTM D 1003	%	18
Water Absorption, 24 hours	ASTM D 570	%	0.15
Poisson's Ratio	ASTM E 132	-	0.38
<b>MECHANICAL</b>			
Tensile Strength, Ultimate	ASTM D 638	psi	9,500
Tensile Strength, Yield	ASTM D 638	psi	9,000
Tensile Modulus	ASTM D 638	psi	340,000
Elongation	ASTM D 638	%	110
Flexural Strength	ASTM D 790	psi	13,500
Flexural Modulus	ASTM D 790	psi	345,000
Compressive Strength	ASTM D 695	psi	12,500
Compressive Modulus	ASTM D 695	psi	345,000
Izod Impact Strength, Notched @ 0.125"	ASTM D 256	ft·lbs/in	18
Izod Impact Strength, Unnotched @ 0.125"	ASTM D 256	ft·lbs/in	60 (no break)
Instrumented Impact @ 0.125"	ASTM D 3763	ft·lbs	47
Shear Strength, Ultimate	ASTM D 732	psi	10,000
Shear Strength, Yield	ASTM D 732	psi	6,000
Shear Modulus	ASTM D 732	psi	114,000
Rockwell Hardness	ASTM D 785	-	M70 / R118
<b>THERMAL</b>			
Coefficient of Thermal Expansion	ASTM D 696	in/in/°F	3.75 x 10 <sup>-5</sup>
Coefficient of Thermal Conductivity	ASTM C 177	BTU·in/hr·ft <sup>2</sup> ·°F	1.35
Heat Deflection Temperature @ 264 psi	ASTM D 648	°F	270
Heat Deflection Temperature @ 66 psi	ASTM D 648	°F	280
Brittleness Temperature from ductile to brittle	ASTM D 746	°F	-40 - -200
Shading Coefficient, clear @ 0.236"	NFRC 100-2010	-	0.97
Shading Coefficient, Gray or Bronze @ 0.236"	NFRC 100-2010	-	0.77
U factor @ 0.236" (summer, winter)	NFRC 100-2010	BTU/hr·ft <sup>2</sup> ·°F	0.85, 0.92
U factor @ 0.375" (summer, winter)	NFRC 100-2010	BTU/hr·ft <sup>2</sup> ·°F	0.78, 0.85
<b>ELECTRICAL</b>			
Dielectric Constant @ 10 Hz	ASTM D 150	-	2.96
Dielectric Constant @ 60 Hz	ASTM D 150	-	3.17
Volume Resistivity	ASTM D 257	Ohm·cm	8.2 x 10 <sup>16</sup>
Dissipation Factor @ 60 Hz	ASTM D 150	-	0.0009
Arc Resistance			
Stainless Steel Strip electrode	ASTM D 495	Seconds	10
Tungsten Electrodes	ASTM D 495	Seconds	120
Dielectric Strength, in air @ 0.125"	ASTM D 149	V/mil	380

4 \*Typical properties are not intended for specification purposes.

# TUFFAK Product Selection Guide



TUFFAK Grade	Key Product Features	Typical Applications
<b>GP</b>	High impact; clarity; and temperature resistant	Industrial glazing, machine guards, structural parts, thermoformed and fabricated components
<b>GP Patterns</b>	Pebble, matte and prismatic surface finishes	Industrial glazing, privacy glazing, signs, displays, and lighting covers
<b>OP</b>	Optical Quality	Face shields, laminates
<b>FI</b>	UL 94 V-0, 5VA; FAA rated; not UV stabilized	Electrical devices, equipment housings, switchgear covers, and interior aircraft components
<b>LF</b>	UL 94 V-0; FAA rated has UV stabilizer	Electrical devices, equipment housings, switchgear covers, light fixtures, aerospace components
<b>FD</b>	FDA compliant for food contact	Machine guards, bulk food bins, candy molds, sneeze guards, hospital trays, bassinets, incubators, and medical device storage containers
<b>SL</b>	Enhanced outdoor weathering performance	Flat and formed sign faces and channel letters
<b>SL Matte</b>	Enhanced outdoor weathering performance with matte texture	Flat and formed sign faces, channel letters and digital displays
<b>LD</b>	LED light diffusion; enhanced outdoor weathering performance	Flat and formed sign faces and channel letters using LEDs
<b>NR</b>	Non-reflective; UV resistant; proprietary matte surface; impact strength	Display and screen protection, signage, lenses, and menu boards
<b>NR-C</b>	Non-reflective; UV resistant; one side hard-coated; textured surface	Display and screen protection, fuel dispensing systems, signage, lenses, and menu boards with improved chemical resistance
<b>UV</b>	High optical quality enhanced outdoor weathering performance and can be cold formed on site	Covered pedestrian walkways, entryway canopies, awnings, skylights, barrel vaults, glazed archways, and sloped, vertical, and curved glazing
<b>SK</b>	Designed as inner light of a dual domed skylight	Awning, skylights, entryway canopies, barrel vaults, sloped, vertical and curved glazing
<b>SK1</b>	Smooth and prismatic optimized to diffuse and distribute light with high light transmission; UV resistant	Awning, skylights, entryway canopies, barrel vaults, sloped, vertical and curved glazing
<b>multi UV</b>	Light weight; high structural strength; multiple geometries for different structural and insulating properties	Greenhouses, solariums and atriums, covered walkways, insulative privacy glazing
<b>AR</b>	Long lasting abrasion and chemical resistance, and outdoor weathering performance	Replacement glazing, industrial guarding, safety components
<b>15</b>	Long lasting abrasion and chemical resistance, and outdoor weathering performance; Fifteen (15) year limited product warranty	Architectural glazing for residential, retail, transportation centers, psychiatric facilities
<b>FC</b>	Cold formable and drape formable; meets ANSI Z26.1 AS-6	Motorcycle and recreational vehicle windscreens, face shields, and formed applications
<b>CG375, CG500, CG750</b>	Meets ASTM F 1915; ASTM F 1233; H.P. White TP 0500	Jails, prisons, detention and psychiatric containment glazing
<b>BR750</b>	Meets UL 752	Ballistic resistant glazing for government, institutional and commercial installations

TUFFAK Grade	Key Product Features	Typical Applications
<b>BR1000</b>	Meets UL 752 Level 2; ASTM F 1233; ASTM F 1915; H.P. White TP 0500	Ballistic resistant glazing for government, institutional, banks and commercial installations
<b>BR1250</b>	Meets UL 752 Level 3; NIJ Level II; ASTM F 1233; ASTM F 1915; H.P. White TP 0500	Ballistic resistant glazing for government, institutional, banks and commercial installations
<b>MS1250</b>	Meets UL 752 Level 6	Ballistic resistant glazing for severe threat
<b>Lumen XT</b>	Superior LED and conventional light diffusion; wide range of diffusion levels	Interior LED and conventional lighting fixtures
<b>Lumen XT-V</b>	Meets UL 94 V-0, 5VA	Interior LED and conventional lighting fixtures
<b>DX-NR</b>	Specifically formulated for superior LED light diffusion with enhanced weathering performance	Exterior LED and conventional lighting fixtures
<b>IR</b>	Meets welding shades 3 and 5; complies with ANSI Z87.1, EN 169: CSA Z94.3	Face shields for flame welding and cutting, general IR protection, welding curtain
<b>MG</b>	0.750" - 2.0" thick for machining, textured surface	Machined parts such as manifolds, insulators, diaphragms, electrical, semiconductor, military applications
<b>WG</b>	0.750" - 2.0" thick, transparent	Sight windows for tanks/vessels, viewports, medical parts, military applications
<b>AU</b>	UV and abrasion resistant; ultra clear; high visible light transmission	Specialty laminates
<b>UC</b>	High light transmission; and high optical quality	Military aircraft canopies, specialty laminates
<b>SQ</b>	High optical quality	High optical quality with specifications tailored to end-use application
<b>HV</b>	UV and abrasion resistant; high optical quality thick gauge sheet; meets ANSI Z26.1 AS-4	Forestry equipment, agricultural and industrial vehicle glazing
<b>TX</b>	Extended UV and abrasion resistant glazing for windows; meets ANSI Z26.1 AS-4 and FMVSS 302	RV, construction, and commercial truck rear windows
<b>BG</b>	UV and abrasion resistant; optical performance meets ANSI Z26.1 AS-4 and FMVSS 302	Bus window glazing
<b>TG</b>	High optical performance with enhanced UV and abrasion resistance; meets FRA 49 CFR 233 & 49 CFR 238 for flammability, smoke, ballistics, and impact	Passenger rail car glazing
<b>Marine 5</b>	High optical clarity; low optical distortion; UV, abrasion, and chemical resistant	Marine flexible enclosures, tent and awning enclosures
<b>VR</b>	High optical quality; low optical distortion; high clarity	Marine flexible enclosures, tent and awning enclosures
<b>Bayblend® MTR</b>	Opaque sheet for mass transit interiors. Meets FRA 49 CFR 238 standards for flame and smoke; meets SMP-800C toxic gas generation	Thermoformed rail interior parts such as structural seating components, wall cladding, window reveals, ceiling panels
<b>Bayblend MTR AG</b>	Opaque sheet with anti-graffiti, scratch, and stain resistance; meets FRA 49 CFR 238 standards for flame and smoke; meets SMP-800C toxic gas generation	Thermoformed rail interior parts such as structural seating components, wall cladding, window reveals, ceiling panels
<b>Bayblend MTR AG Deco</b>	Opaque sheet with anti-graffiti, scratch and stain resistance customizable first service print. Meets FRA 49 CFR 238 standards for flame and smoke; meets SMP-800C toxic gas generation	Thermoformed rail interior parts such as structural seating components, wall cladding, window reveals, ceiling panels
<b>FP</b>	Long lasting abrasion, chemical and outdoor weathering performance; customizable edge fritting	Heavy equipment cab safety glazing, marine and mass transit glazing
<b>AL</b>	High optical quality; abrasion, chemical and UV resistant	Automotive laminates

# Chemical / Environmental Resistance



# Chemical / Environmental Resistance



The chemical and environmental resistance of TUFFAK depends on the unique combination of factors and variables it encounters in its application.

Outlined below is an overview of its primary outside influencers, and common types of potential damage. A summary of laboratory tests designed to meet its practical requirements, as well as its resistance to a wide range of chemicals and substances, is also provided.

Your Plaskolite Representative, with the support of our Technical Service Group, is available to work with you to evaluate your specific application.

## Influencing parameters

### TUFFAK properties are influenced chiefly by:

- » The composition of chemical ingredients
- » Temperature
- » Duration of exposure
- » The level of internal or applied stress and strain

## Types of damage

TUFFAK can sustain several distinct types of damage, including swelling, dissolution, stress cracking and molecular degradation. Circumstances under which these potential types of damage can occur are detailed below. Different chemicals may act simultaneously on TUFFAK sheet causing one or more types of damage.

## Swelling or dissolution

When low-molecular, aromatic, halogenated and polar components migrate into the polycarbonate, the damage can range from a tacky surface, to swelling, to complete dissolution.

## Stress cracking

Even in small quantities, a number of chemicals can penetrate the surface of TUFFAK. This may result in stress cracks that affect the formed or fabricated part's appearance or mechanical properties.

With transparent grades of TUFFAK, stress cracks are generally easy to detect. In opaque grades, it may be difficult to detect them. Stress cracks can act like a notch, leading to significant deterioration in several mechanical properties, particularly impact, flexural and tensile performance. Laboratory tests such as impact or flexural strength can be used as indicators for mechanical property degradation.

Temperature and the duration of exposure are key influencers in the potential cracking of TUFFAK. As temperature rises, the time that elapses before damage occurs shortens. The exposure time required for initial damage ranges from a few seconds to more than 1000 hours due to the chemical involved, temperature, and stress level. For example, when formed or fabricated parts with pronounced stresses are immersed in aggressive solvents, stress cracks will occur in less than one minute.

It is possible for a component within a solid to migrate to polycarbonate through long-term contact and cause damage. One example is the contact between polycarbonate and plasticized PVC. Plasticizers within PVC, such as phthalates can trigger stress cracking and result in damage to the polycarbonate.

## Molecular degradation

Many of TUFFAK properties are determined by the size of its molecules. If an incompatible chemical causes a reduction in molecular weight, mechanical property degradation can occur. The molecular weight has virtually no influence on electrical properties and only a slight influence on thermal properties.

Solutions with a high pH (bases) can act to lower the molecular weight of polycarbonate. Low pH (acids) solutions typically do not degrade the molecular weight. Ammonia and amines are aggressive towards polycarbonate.

Plaskolite laboratories have tested a series of chemicals and commercial products to determine their compatibility with polycarbonate. The results of TUFFAK resistance to substances are included in the following table (pages 10-13).

Laboratory tests supply information on the formulation tested. The composition of many commercial products can change over time.

## Oxidative damage

TUFFAK is relatively stable toward oxidizing agents such as oxygen, nitric acid, and hydrogen peroxide.

## Resistance

TUFFAK's resistance to chemicals, common industrial cleaners, pharmaceuticals, household and cosmetic substances, is dependent on the ingredients in the product, as well as the temperature and duration of exposure. The following section provides a general overview of resistance to these commonly used materials. If you require additional information, please contact your Plaskolite representative.

### » Resistance to sealing compounds, adhesives and plastics

TUFFAK's resistance to sealants, adhesives and plastics is largely dependent on the presence of aggressive components, such as plasticizers (e.g., phthalates) or solvents, which can migrate into polycarbonate.

### » Resistance to paints

Solvents in paints may cause stress cracking or swelling depending upon the solvent and the flash-off and drying conditions. It is possible to formulate paints with solvents that do not cause damage. In some applications, painting can increase the chemical resistance of the finished part.

Two component paints are resistant if the individual components do not cause damage to TUFFAK in the short period between the application and curing. The SDS can be used to identify the chemical composition of the paint.

### » Resistance to cleaning and washing agents

TUFFAK is resistant to most household soaps but not those containing amines, ammonia and sodium hydroxide.

### » Resistance to disinfectants, drugs and cosmetics

TUFFAK may be damaged by disinfectants, drugs and cosmetics, which contain solvents or active ingredients that are incompatible with polycarbonate. For example, nail polish and nail polish remover will cause damage to the material.

If the product ingredients are known, it is possible to estimate the compatibility with TUFFAK. However, it is recommended to put the finished part through a practical test if no data is available. Refer to the compatibility table (pages 10-13) for resistance levels.

# Chemical / Environmental Resistance



## Testing to meet practical requirements

The compatibility information presented in this section should be used as a starting point for determining the integrity and durability of your application. Testing is essential if finished TUFFAK components are likely to encounter aggressive chemicals during use. The internal and applied stress in a formed or fabricated part, as well as duration of chemical exposure, can lead to very different results.

## Compatibility assessment methods

The data shown in the compatibility table (pages 10-13) was generated using DIN 53449-3. This method uses test pieces of 80 x 10 x 4 mm TUFFAK sheet clamped to a curved fixture. The fixture applies a graduated strain ranging from 0 to 2%.

## Assessment criteria

The information in the compatibility table is based on exposure to chemicals at 23°C and a range from 0-2% strain. Components that lead to damage with a strain of  $\epsilon < 1.0\%$  are classified as incompatible.

The results shown in the following tables are based on a one-time test. Change in the composition by the producers of these substances can change the results.

Please contact your Plaskolite representative or the Technical Service Group at 800.628.5084 with any questions, or if you require additional information.

# Chemical / Environmental Resistance



## Legend

### Explanation of the symbols:

- ⊕ Resistant
- ⊖ Partially resistant
- Not Resistant

## Chemicals

Acetaldehyde	-
Acetic acid, up to 10% solution	⊕
Acetone	-
Acetylene	⊕
Acrylonitrile	-
Allylalcohol	⊖
Alum	⊕
Aluminum chloride, saturated aqueous solution	⊕
Aluminum oxalate	⊕
Aluminum sulphate, saturated aqueous solution	⊕
Ammonia	-
Ammoniacal liquor	-
Ammonium chloride, saturated aqueous solution	⊕
Ammonium nitrate, saturated aqueous solution	⊕
Ammonium sulphate, saturated aqueous solution	⊕
Ammonium sulphide, saturated aqueous solution	-
Amylo acetate	-
Aniline	-
Antimony chloride, saturated aqueous solution	⊕
Arsenic acid, 20% solution	⊕
Benzaldehyde	-
Benzene	-
Benzoic acid	-
Benzyl alcohol	-
Borax, saturated aqueous solution	⊕
Boric acid	⊕
Bromic benzene	-
Bromine	-
Butane (liquid or gaseous)	⊕
Butyl acetate	-
Butanol	⊕
Butylene glycol	⊕
Butyric acid	-
Calcium chloride, saturated aqueous solution	⊕
Calcium hypochloride	⊕
Calcium nitrate, saturated aqueous solution	⊕
Calcium-soap, fat/pure	⊕
Carbon acid, wet	⊕
Carbon monoxide	⊕
Chlorine benzene	-
Chlorine gas, dry	⊖
Chlorine gas, wet	-
Chlorine lime slurry	⊕

Chlorine lime, 2% in water	⊕
Chloroform	-
Chrom alum, saturated aqueous solution	⊕
Chromic acid, 20% in water	⊕
Citric acid	⊕
Copper sulphate, saturated aqueous solution	⊕
Cresol	-
Cupric chloride, saturated aqueous solution	⊕
Cuprous chloride, saturated aqueous solution	⊕
Cyclo hexane	-
Cyclo hexanol	⊖
Cyclo hexanone	-
Dekaline	⊕
Diamyl phthalate	-
Dibutyl phthalate (plasticizer)	-
Diethylene glykol	⊕
Diethyllether	-
Diglycolic acid, saturated aqueous solution	⊕
Dimethyl formamide	-
Dinonyl phthalate (plasticizer)	⊖
Diocetyl phthalate (plasticizer)	⊖
Dioxane	-
Diphyl 5, 3	⊖
Ether	-
Ethyl alcohol, 96% pure	⊕
Ethyl amine	-
Ethyl bromide	-
Ethylene chlorohydrene	-
Ethylene chloride	-
Ethylene glykol	⊕
Ferritrichloride, saturated aqueous solution	⊕
Ferro bisulphate	⊕
Formaline, 10%ig	⊕
Formic acid, 30%	⊖
Gasoline	⊕
Glycerine	⊖
Glycol	⊕
Heptane	⊕
Hexane	⊕
Hydrochloric acid, 20%	⊕
Hydrochloric acid, conc.	-
Hydrofluoric acid, 5%	⊕
Hydrofluoric acid, conc.	-
Hydrofluorosilicic acid, 30%	⊕
Hydrogen peroxide, 30%	⊕
Iodine	-
Isoamyl alcohol	⊖
Isopropyl alcohol	⊕
Lactic acid, 10% in water	⊕
Lead tetraethylene, 10% in gasoline	⊖
Lighting gas	⊕

# Chemical / Environmental Resistance



Ligroin (hydrocarbon compound)	+	Propionic acid, conc.	-
Lime milk, 30% in water	O	Propyl alcohol	+
Magnesium chloride, saturated aqueous solution	+	Pyridine	-
Magnesium sulphate, saturated aqueous solution	+	Resorcin oil solution, 1%	+
Manganous sulphate, saturated aqueous solution	+	Carbon disulphide	-
Mercuro chloride, saturated aqueous solution	+	Hydrogen sulphide	+
Mercury	+	Soda	+
Methacrylic acid-methyester (MMA)	-	Sodium bicarbonate, saturated aqueous solution	+
Methane	+	Sodium bisulphate, saturated aqueous solution	+
Methanol	-	Sodium bisulphide, saturated aqueous solution	+
Methyl amine	-	Sodium carbonate, saturated aqueous solution	+
Methyl ethyl ketone (MEK)	-	Sodium chlorate, saturated aqueous solution	+
Methylene chloride	-	Sodium chloride, saturated aqueous solution	+
Nitric acid, 10%	+	Sodium hydroxide	-
Nitric acid, 10-20%	O	Sodium hypochloride, 5% in water	+
Nitric acid, 20%	-	Sodium sulphate, saturated aqueous solution	+
Nitric Gas, dry	-	Sodium sulphide, saturated aqueous solution	O
Nitrobenzene	-	Styrene	-
Oxalic acid, 10% in water	+	Sublimate, saturated aqueous solution	+
Oxygen	+	Sulphur	+
Ozone	+	Sulphur dioxide	O
Pentane	+	Sulphuric acid, 50%	+
Perchloric acid, 10% in water	+	Sulphuric acid, 70%	O
Perchloric acid, concentrated	O	Sulphuric acid, conc.	-
Perchloro ethylene	-	Sulphurous acid, 10%	-
Perhydrol, 30%	+	Sulphuryl chloride	-
Petroleum	O	Tartaric acid, 10%	+
Petroleum ether	O	Tetrachlorocarbon	-
Petroleum spirit	+	Tetrachloroethane	-
Phenol	-	Tetrahydrofurane	-
Phenyl ethyl alcohol	-	Tetraline	-
Phosphor trichloride	-	Thiophene	-
Phosphoric acid, conc.	+	Toluene	-
Phosphoric oxichloride	-	Trichloro acetic acid, 10%	O
Potassium aluminum sulphate, saturated aqueous solution	+	Trichloroethyl amine	-
Potassium bichromate, saturated aqueous solution	+	Trichloroethyl phosphate (plasticizer)	O
Potassium bromide, saturated aqueous solution	+	Trichloroethylene	-
Potassium carbonate, saturated aqueous solution	+	Tricresyl phosphate (plasticizer)	-
Potassium chloride, saturated aqueous solution	+	Urea, saturated aqueous solution	+
Potassium cyanide	-	Water	+
Potassium hydroxide	-	Xylene	-
Potassium metabisulphide, 4% in water	+	Zinc chloride, saturated aqueous solution	+
Potassium nitrate, saturated aqueous solution	+	Zinc oxide	+
Potassium perchlorate, 10% in water	+	Zinc sulphate, saturated aqueous solution	+
Potassium permanganate, 10% in water	+		
Potassium persulphate, 10% in water	+		
Potassium rhodanide, saturated aqueous solution	+		
Potassium sulphate, saturated aqueous solution	+		
Propane gas	+		
Propargyl alcohol	+		
Propionic acid, 20%	+		

# Chemical / Environmental Resistance



## Disinfectants

Accel TB	-
Baktol®, 5%	+
Carbolic acid	-
Chloroamine	+
Clorox® BROAD SPECTRUM Quaternary Disinfectant Cleaner	-
Clorox® Healthcare FUZION Cleaner Disinfectant	-
Clorox® Healthcare Bleach Germicidal Cleaner	-
Delegol®, 5%	+
Dimamin T, 5%	O
Hydrogen peroxide	+
Iodine tincture	O
Lyoform, 2%	+
Lysol® Brand III Disinfectant Spray (original)	-
Maktol®	+
Merfen®, 2%	+
Oktozon®, 1%	+
PDI® Super Sani-Cloth® Disposable Wipes	-
Perhydrol	+
PeridoxRTU® Sporicidal Disinfectant	-
Resorcinol solutions, 1%	+
Safetec Surface Safe Wipes	-
Sagrotan®, 5%	O
Spirit, pure	+
Steriplex® SD	-
Sublimate	+
TB-Lyoform	-
Trosilin G extra®, 1, 5%	+
ZEP® 40 Non-Streaking Cleaner	-
ZEP® SPIRIT II	-
Zephirol®	O

## Nutrition

Allspice	-
Apple juice	+
Beef sebum	+
Beer	+
Beets syrup	+
Brandy, 38%	+
Butter	+
Chocolate	+
Cinnamon	+
Clove	-
Cod-liver oil	+
Coffee	+
Common salt	+
Fish	+
Fruit juice	+
Fruit syrup (Raspberry)	+
Gherkins	+
Grape sugar	+
Grapefruit juice	+
Juniper berry	+
Lard	O
Linseed oil	+
Liquor	+
Margarine	+
Meat	+
Milk	+
Mineral water	+
Mustard	+
Nutmeg	-
Onion	+
Orange juice	+
Paprika	+
Pepper	+
Rum	+
Salad oil	+
Syrup	+
Sugar solution, saturated aqueous solution	+
Tea	+
Tobacco	+
Tomato juice	+
Tomato puree	+
Vanilla	+
Vegetable juice	+
Vegetable oils	+
Vinegar	+
Vodka	+
Water	+
Wine	+
Worcestershire sauce	+

## Pharmaceutics and cosmetics

Blood plasma	+
Delial-Sunmilk®	+
Botanicare® Hydroplex	+
Iodine tincture	O
Klosterbalsam	+
Lanoline	+
Menthol, 90% in Alcohol	O
Nail polish	-
Nail polish remover	-
Odol-mouthwash®	+
Periston blood substitute®	+
Vaseline	+
Vicks® VapoRub®	+

# Chemical / Environmental Resistance



## Washing and cleaning agents

Household soap	+
Top Job	+
Joy®	+
Palmolive Liquid®	+

## Technical oils and fats

Camphor oil	-
Castor oil	+
Cod-liver oil	+
Drilling oil	-
Fish oil	+
Fuel oil	O
Lubricant based on paraffin	+
Paraffin oil	+
Sodium soap fat	+

## Miscellaneous

Battery acid	+
Blood	+
Castor oil	+
Cement	+
Freon® 113	+
Gasoline	O
Natural rubber	+
Oleic acid, conc.	+
Polishing wax	+
Polyethylene	+
Polyvinylchloride, (containing plasticizer)	O
Sea water	+
Starch	+
Weak acid >4.7 pH	+
Weak base <9.5 pH	O
Tannic acid	-



## Cleaning Recommendations

# Cleaning Recommendations



## TUFFAK cleaning instructions

Periodic cleaning of TUFFAK is recommended to prolong the service life of your material. To minimize the risk of damage, use only compatible household cleaners and correct cleaning procedures as outlined below.

TUFFAK GP polycarbonate mars easily with wiping action. TUFFAK 15, TUFFAK AR, and Hygard laminate sheets are hard coated, abrasion and mar resistant polycarbonate products that offer a high degree of surface hardness and abrasion resistance. These products provide superior protection against unintentional chemical attack. However, the use of abrasive, gritty cleaners or hard cleaning implements (e.g., hard brushes, scrapers, squeegees) should be avoided to eliminate the possibility of scratching the coating.

## Compatible cleaners

The following cleaning agents are compatible with TUFFAK polycarbonate sheet products when used according to the manufacturer's recommendations:

- » Top Job
- » Joy®
- » Palmolive Liquid®
- » Windex® Ammonia free

Top Job and Joy are registered trademarks of Proctor & Gamble, Palmolive is a registered trademark of Colgate Palmolive, Windex is a registered trademark of Drackett Products.

## General cleaning instructions:

- » Thoroughly pre-rinse with warm water to loosen and wash away surface residue, grit and grime.
- » Using a soft microfiber cloth or moist non-abrasive sponge, gently wash with a mild diluted soap or detergent.
- » Rinse thoroughly with lukewarm, clean water. To prevent water spots, thoroughly dry the glazing with a dry soft cloth.

## Removing heavy oils and tars:

- » Thoroughly pre-rinse with warm water to loosen and wash away surface residue, grit and grime.
- » With a 50/50 isopropyl alcohol-water mixture, gently rub the area with a soft non-abrasive cloth.
- » Immediately rinse thoroughly with lukewarm clean water. To prevent water spots, thoroughly dry the glazing with a dry soft cloth.

## Removing graffiti, paint, marker, inks and glazing compounds:

- » Thoroughly pre-rinse with warm water to loosen and wash away surface residue, grit and grime.
- » Using Naphtha VM&P grade, Isopropyl Alcohol or Butyl Cellosolve™, gently rub the area with a soft, non-abrasive cloth. Do not apply solvent cleaners under direct sunlight or during high temperatures.
- » Immediately rinse thoroughly with lukewarm clean water. To prevent water spots, thoroughly dry the glazing with a dry soft cloth.

## Removing adhesive-backed labels:

- » Isopropyl Alcohol, Naphtha VM&P grade or Kerosene will help lift stickers and adhesives.
- » Immediately rinse thoroughly with lukewarm clean water. To prevent water spots, thoroughly dry the glazing with a dry soft cloth.

## Important reminders

- » Do not clean TUFFAK with any cleaners other than those on the approved, compatible list included in this guide, or those tested and found compatible.
- » Do not use abrasive cleaners.
- » Do not use high alkaline cleaners (high pH or ammoniated).
- » Do not leave cleaners sitting on TUFFAK for periods of time; rinse off immediately.
- » Do not apply cleaners under direct sunlight or at elevated temperatures.
- » Do not use scrapers, squeegees, razors or other sharp instruments as they may permanently scratch TUFFAK.
- » Do not dry rub or dry clean TUFFAK, as sand and dust particles clinging to the exterior of the glazing may scratch its surface. An Anti-Static Canned-Air Ionizer can reduce electro static charge buildup on TUFFAK, and aids in reducing dirt and dust buildup that can hinder cleaning.

**Contact the Plaskolite Technical Service Group at 800.628.5084 with any questions.**

## TECH TIP:

The edges of coated polycarbonate sheet are not protected with an abrasion and chemical resistant hard coating. Do not allow cleaning solutions and solvents to pool along the edges for any length of time. Always rinse edges thoroughly with generous amounts of lukewarm clean water.

## Removing scratches

Deep scratches and gouges made by sharp objects such as keys, screwdrivers, and knives cannot be repaired. Fine scratches may be reduced in severity or cosmetically hidden by using a buffering compound such as NOVUS® 2 Plastic Fine Scratch Remover, followed by a cleaning and polishing agent like NOVUS® 1. However, for abrasion resistant coated products, buffering the surface is not recommended. Buffering these scratched sites worsens the condition and further damage the coating. Once the coating is removed, it cannot be repaired and buffering may optically distort the window.

# Fabrication

CAUTION  
DISCONNECT POWER  
BEFORE REMOVING  
THIS COVER/DOOR

DANGER  
HANDS OUT

DANGER  
Keep hands and  
fingers away

# Fabrication – Introduction



## Cutters

TUFFAK sheet products easily fabricate using standard cutting tools. Carbide-tipped cutters are recommended. Always use properly sized, sharp cutting tools.

## Cooling

Cooling TUFFAK sheet while fabricating is not typically required. In the event of localized overheating when fabricating, only use compressed air or water mist. Avoid cutting fluids of any type. The additives in these products are largely incompatible and can cause chemical stress cracking.

## TECH TIP:

Wear eye protection, and ensure equipment has safety guarding. Stock feed rates must be carefully controlled as an excessive rate causes vibration and may crack the part.

## Dimensional accuracy

The rate at which TUFFAK sheet expands is higher than materials such as glass and metal. It has a movement rate of 0.060" per 12 inches of linear dimensions, over a 70°F temperature change. As a result, the dimensions should always be checked at room temperature.

## Protective masking

TUFFAK sheet comes with protective masking. This film guards against surface damage during shipment/handling as well as fabrication. This masking should be left on during fabrication.

Masking cannot withstand direct outdoor exposure for prolonged periods and must be removed soon after installation. If not removed, the film will eventually degrade and may be difficult or impossible to remove. Storing sheet outdoors is not recommended for this reason.

Remove the masking prior to doing any type of heat processing; for further guidance on this subject please contact Plaskolite Technical Service Group for more information.

## SAWING, SHEARING, DRILLING, MILLING, ROUTING, DIE CUTTING/PUNCHING


### CIRCULAR SAWING

As shown in the accompanying illustration, use a carbide-tipped, circular saw blade with triple-chip tooth design, which cuts clean and lasts longer than high strength steel. Blade is hollow-ground and slotted for expansion and cooling.

#### Circular saw blade and cutting

Cutting speed (ft/min)	5000 - 6000
4" Blade	8 - 10 teeth/inch
8 - 10" Blades	6 - 8 teeth/inch

#### Triple-chip grind



#### Circular saw troubleshooting

##### PROBLEM: Melting or Gummed Edges

##### SUGGESTED SOLUTIONS:

1. Increase blade tooth size
2. Reduce saw speed
3. Increase feed rate
4. Use compressed air to cool blade
5. Inspect blade for sharpness
6. Check blade-fence alignment
7. Reduce number of sheets in stack

##### PROBLEM: Chipping

##### SUGGESTED SOLUTIONS:

1. Decrease blade tooth size
2. Increase saw size
3. Provide better clamping/support for sheet stack
4. Reduce feed rate
5. Check blade and arbor for wobble
6. Inspect blade for sharpness

#### Circular saw blade suppliers:

**Dino Saw Company**  
340 Power Ave.  
Hudson, NY 12534  
518 828-9942  
[www.dinosaw.com](http://www.dinosaw.com)

**General Saw Corp.**  
2518 Andalusia Blvd.  
Cape Coral, FL 33909  
800 772-3691  
[www.generalsaw.com](http://www.generalsaw.com)

**FTM, Inc.**  
327 Industrial Drive  
Placerville, CA 95667  
530 626-1986  
[www.thefabricatorssource.com](http://www.thefabricatorssource.com)

# Fabrication



## BAND SAWING

Band sawing is preferred for cutting contour and irregular shapes.

### General guidelines:

- » Use precision or standard blades for sheet and parts made from thin gauge
- » Use buttress or skip-tooth blades for sheets thicker than 1/8 inch
- » Choose band-saw blades with generous set to reduce friction and heat buildup
- » Cool the cut junction with air or a water mist
- » Control the feed rate carefully to prevent binding and gumming
- » Use saw guides whenever possible

### Band saw troubleshooting

#### PROBLEM: Melting or Gummed Edges


#### SUGGESTED SOLUTIONS:

1. Increase blade tooth size
2. Reduce saw speed
3. Use compressed air to cool blade
4. Check blade sharpness

#### PROBLEM: Chipping

#### SUGGESTED SOLUTIONS:

1. Decrease blade tooth size
2. Slow down stock feed rate
3. Provide better clamping/support to eliminate vibration
4. Check blade sharpness




Band saw blade design				
Part thickness (inch)	Tooth type	Pitch (teeth/inch)	Band speed (ft/min)	
< 1/8	Precision or Standard	8 - 12	2,000	
1/8 - 1/4	Buttress or Skip Tooth	5 - 6	1,500	
> 1/4	Buttress or Skip Tooth	3 - 4	1,000	

## SHEARING

TUFFAK sheet up to 1/4 inch thick can be sheared. Sheared edges have a burred and rolled cut that is highly stressed and should be saw trimmed to prevent future cracking.

### Important considerations for shearing:

- » A guillotine blade on a fixed bed cuts a cleaner edge than a two blade shear
- » 45-degree rake angle blade recommended
- » Clearance between the blade and bed should be no more than 0.001-0.002 inch
- » If cracks develop upon shearing, consider warming the material first; inspect blade
- » Shearing flame retardant product is not recommended as the additives in the sheet reduce its ductility. Warming material may help prevent cracking but does not guarantee success



# Fabrication




## DRILLING

While standard drills and bits can be used with TUFFAK sheet, those specifically designed for plastics perform with greatest precision. They have wide, polished flutes to reduce friction, as well as spiral or helix designs to remove chips quickly.


- » Drill-point angles typically range between 60 and 90 degrees
  - Smaller angles for smaller holes and larger angles for larger holes
- » Drilling speeds range between 100 and 200 feet per minute, however feed rates can be increased under ideal conditions of proper cooling, sharp drills and efficient chip removal

### General guidelines for drilling TUFFAK sheet:

- » Use carbide-tipped drills, they resist gumming and maintain edge sharpness longer than standard drills
- » Drill holes slightly oversized
- » Allow distance between sheet edge and drilled hole to be at least two times the diameter of hole
- » Do not use cutting fluids; use cool forced air
- » **Countersink is not recommended, counter-bore is acceptable**



## Drill bit design



Drill (inch)	Feed (inch/rev)	Drill speed (RPM)
Up to 1/8	0.001 - 0.002	1750
1/8 to 1/4	0.002 - 0.004	1750 - 1500
1/4 to 1/2	0.004 - 0.006	1500 - 500
1/2 to 1	0.006 - 0.008	500 - 350

### Common drilling problems and remedies

Problem	Probable cause	Remedy
Hole too large	1. Unequal angle on length of cutting edge 2. Burr on drill	1. Properly reground drill 2. Properly reground drill
Rough or burred hole	1. Dull drill 2. Improperly ground drill 3. Too fast feed	1. Reground properly 2. Reground properly 3. Reduce feed
Breaking of drill	1. Feed too fast in relation to spindle speed 2. Dull drill-grabs in work 3. Inadequate chip cleaning	1. Reduce feed or increase speed 2. Reground drill 3. Check application setup
Chipping of high-speed drill	1. Improper heat treatment after regrounding 2. Too coarse feed	1. Follow manufacturers' recommendations 2. Reduce feed

## Specialty drill bit suppliers:

### Onsrud Cutter

1081 S. Northpoint Blvd.  
Waukegan, IL 60085  
800 234.1560  
[www.onsrud.com](http://www.onsrud.com)

### Craftics, Inc.

2804 Richmond Dr.  
Albuquerque, NM 87107  
505 338.0005  
[www.craftics.net](http://www.craftics.net)

### FTM, Inc.

327 Industrial Drive  
Placerville, CA 95667  
530 626-1986  
[www.thefabricatorssource.com](http://www.thefabricatorssource.com)

# Fabrication



## MILLING

Milling is used to remove large volumes of plastic with relatively high accuracy and precision. Mounted in a drill press, an end mill can plunge repeatedly to a preset depth to produce parts that are flush and smoothly trimmed. For best results, use high-speed end mills with four cutting flutes and a 15-degree rake angle. Always keep mills sharp and well-polished to reduce friction.

Milling TUFFAK sheet typically works best at feed speeds of 5–10 inches/minute and cutting speeds of between 100 and 200 inches/minute.

Carbide cutters generally provide smoother finishes and allow for higher feed rates. Special cutters designed specifically for plastics produce the smoothest finishes at the fastest feed rates. Check with your cutter supplier for the latest designs for polycarbonate.

### Consider the following when milling TUFFAK sheet:

- » Excessive feed rates can cause rough surfaces
- » Insufficient feed rates can generate too much heat and cause part melting, distortion or poor surface quality
- » Compressed air stream or water mist helps to remove heat and prevent buildup
- » Improper milling can induce high stress levels, causing future problems

### TECH TIP:

Consider annealing milled parts in cases where the machining stresses are known to be high.



# Fabrication



## ROUTING

Router cutting produces a smooth edge on TUFFAK sheet and easily cuts curved or irregular shapes. Use a recommended router speed of 20,000-25,000 rpm, with straight 2- or 3-fluted carbide-tipped or high-speed bits with diameters 1/4 inch to 1/2 inch.

### General guidelines for router cutting

#### TUFFAK sheet:

Router bit design	
Clearance angle	5 - 10°
Rake angle	0 - 10°
Cutting speed (rpm)	20,000 - 25,000



**Important:** Feed the sheet against the router bit rotation and use a fence for sizing when making straight cuts.

#### Specialty router bit suppliers:

##### Onsrud Cutter

1081 S. Northpoint Blvd.  
Waukegan, IL 60085  
800 234.1560  
[www.onsrud.com](http://www.onsrud.com)

##### Boshco, Inc.

2 Sterling Road  
North Billerica, MA 01862  
978 667.1911  
[www.boshco.com](http://www.boshco.com)

##### Dino Saw Company

340 Power Ave.  
Hudson, NY 12534  
518 828-9942  
[www.dinosaw.com](http://www.dinosaw.com)

## DIE CUTTING / PUNCHING

Types of dies used in cutting TUFFAK sheet include steel-rule, punch and clicker in gauges up to 0.080 inch. Steel-rule dies trim lighter-gauge parts and clicker dies perform heavier-gauge cuts and continuous cuts in sheet. To obtain a clean cut in most applications, maintain a clearance between the punch and die of about 0.005 inches.

### General guidelines when die cutting, punching or blanking TUFFAK sheet:

- » For best results, consider warming the part first before die cutting, punching or blanking
- » Maintain sharp cutting edges for cleanest cut and to avoid creating notches and scratches that could later act as stress concentrators
- » Avoid sharp radii in the corners of non-circular cut-outs
- » Die cutting, punching or blanking parts made of flame retardant grade sheet is not recommended

Use 3 pt (0.042") thick steel to fabricate steel-rule die. Flush or center bevel-ground rule provides a clean cut. Facet-ground steel rule is used to cut >0.060 inch TUFFAK sheet. The center bevel rule is the most common and provides the longest life in terms of wear. Cleaner cuts can be attained by using a facet bevel rule. The longer bevel reduces material displacement, especially with thick material, while the broad tip remains sharp. The flush bevel rule also provides clean cuts, but has a weak tip.


that is susceptible to roll-over. To maximize both cut quality and rule longevity, the side bevel rule is recommended.

#### Laser


Laser cutting TUFFAK can lead to slight discoloration in the cut edge. Contact your laser equipment manufacturer for additional advice on laser settings for cutting or marking of polycarbonate. Adhere to proper safety procedures when laser cutting. The work should be performed in a space with exhaust hoods and good ventilation.

#### TECH TIP:

TUFFAK sheet should be stored in a well-protected, ventilated area with no direct exposure to sunlight or harsh weather conditions. If temporarily stored outdoors, sheets should be covered with a heat reflecting, opaque covering.



# Fabrication Laminate & Heavy Gauge Sheet



# Fabrication – Laminate & Heavy Gauge Sheet



Hygard® laminates and TUFFAK WG and MG plate products are designed for heavy fabrication.

It is possible to fabricate parts with tight tolerance design using standard cutting tools. Use carbide-tipped cutters for greater durability and a cleaner cut edge. Leave the masking on the product while fabricating to protect against surface damage. Remove masking soon after installation as prolonged outdoor exposure degrades the film making it difficult or impossible to remove.


Proper fabricating practices are especially important when cutting parts intended for security applications. This ensures product integrity with respect to strength properties and performance ratings. Sharp cutting tools are important, as is feed rate control. To avoid material overheating, decrease cutting speed and feed rate.

## CIRCULAR SAWING

Use a carbide-tipped, circular saw blade with triple chip tooth design. It allows for cleaner cuts and greater durability than high-strength steel. Blade is hollow-ground, and slotted for expansion and cooling. Recommended blade cutting speed is 5000-6000 ft/min.

### Circular saw blade and cutting

Cutting speed (ft/min)	5000 - 6000
Blade	~3 teeth/inch



### TECH TIP:

The edges of Hygard® laminates are not protected with abrasion and chemical resistant hard coating. Do not allow cleaning solutions and solvents to pool along the edges for any length of time. Always rinse edges thoroughly with generous amounts of lukewarm, clean water.

### Circular saw troubleshooting

#### PROBLEM: Melting or Gummed Edges

#### SUGGESTED SOLUTIONS:

1. Increase blade tooth size
2. Reduce saw speed
3. Increase feed rate
4. Use compressed air to cool blade
5. Inspect blade for sharpness
6. Check blade-fence alignment
7. Reduce number of sheets in stack

#### PROBLEM: Chipping

#### SUGGESTED SOLUTIONS:

1. Decrease blade tooth size
2. Increase saw size
3. Provide better clamping/support for sheet stack
4. Reduce feed rate
5. Check blade and arbor for wobble
6. Inspect blade for sharpness


# Fabrication – Laminate & Heavy Gauge Sheet



## BAND SAWING

Hygard laminates, TUFFAK WG and MG products, can be band saw cut with blades having 8-12 teeth per inch. Carefully choose feed rates and blade speed to avoid gumming or melting the plastic edge.

Pitch (teeth/inch)	Band speed (ft/min.)	Blade set (inch)
8 - 12	2500 - 3000	0.020 - 0.030



## TECH TIP:

Solvent polishing edges of a laminated sheet is not recommended due to the possibility of the TPU bonding layer absorbing the solvent and swelling, resulting in the potential delamination of the product. Microcracking may also occur along solvent polished edges.

## TECH TIP:


Laser cutting of Hygard® laminates is not recommended due to increased stress level and higher risk for discolored edges. Water jet cutting of laminates is not recommended due to the potential for delamination.

## DRILLING

While standard drills and bits can be used when fabricating Hygard laminates, TUFFAK WG and MG products, those specifically designed for use with plastics perform with greater precision. Drills for plastics generally have wide, polished flutes to reduce friction, as well as spiral or helix designs to remove chips quickly.

- » Use drill-point angles larger than 90 degrees

### Drill bit design



### General guidelines for drilling Hygard laminates, TUFFAK WG and MG:

- » Use carbide-tipped drills, they resist gumming and maintain edge sharpness longer than standard drills
- » Avoid cutting fluids; most are not compatible with polycarbonate
- » Cool work if necessary by forced-air stream
- » Avoid drilling into the edge of laminated sheets due to possible loss of interlayer adhesion

Use sharp drills for cleanest cut and frequently clear the hole of chips. Avoid overheating as stress buildup in the material may have an adverse effect on mechanical properties compromising product performance and reliability. If drilling holes, place them no closer than 2 times the diameter of the hole from the edge. Avoid holes in parts intended for ballistic rated applications.

Hole diameter	Drill speed (rpm)
1/8"	1750
1/4"	1050 - 1500
1/2"	350 - 500

## RESOURCE ON DRILLING AND ROUTER CUTTING:

<https://www.onsrud.com/plusdocs/Doc/list.html?pg=0&sf=code&sd=d&model.category=TECH>

# Fabrication – Laminate & Heavy Gauge Sheet



## MILLING/ROUTING

To cut clean edges on Hygard laminates and TUFFAK WG and MG, use straight, 2-3 fluted carbide tipped or high-speed bits, and router speeds of 20,000- 25,000 rpm. Feed sheet against the router bit rotation at a controlled rate to avoid overheating, minimize vibration and produce a smooth part edge. Use a fence for sizing when making straight cuts.

## Summary on cutting:

- » Use only sharp cutters
- » Drill holes slightly oversized
- » Drill holes off sheet edge by distance at least 2 times diameter of hole
- » Countersink is not recommended, counter-bore is acceptable in heavy gauge sheet
- » Countersink and counter-bore is not recommended for Hygard laminates
- » As cooling medium use forced air, not cutting fluids
- » Do not allow material to overheat
- » Cut edges must be smooth; sand coarse surfaces and chatter marks
- » Leave masking on product during fabrication, remove soon after installation
- » Use cleaners compatible with polycarbonate. If unsure, consult with manufacturer before use

## FRAME DESIGN



Select a metal frame that matches the same level of security-rated protection as the specified Hygard laminate.

Product performance relies heavily on the method of attachment, the assembly and the potential for thermal expansion.

### Corner design


Mitered corners require added bracing. Attach metal angle bracing at the corners to strengthen the overall frame.

For optimal frame design, use a continuous metal extrusion.



## Glazing recommendations

- » Frame system must meet or exceed Hygard laminate ballistic rating
- » Hygard laminate dimension must allow for at least 1 inch edge engagement
- » Use only gaskets, tapes and sealants compatible with polycarbonate
- » Use setting block strips of polycarbonate, EPDM, neoprene or Santoprene® synthetic rubber
- » Remove protective masking soon after completing the installation, as prolonged exposure to the outdoors will degrade the film making it difficult or impossible to remove



# Thermoforming

# Thermoforming



Thermoforming is a cost-effective and practical processing method for producing three-dimensional shapes from a flat thermoplastic sheet using heat and pressure. Thermoformed parts can be found across transportation, signage, architectural, specialty and industrial markets.

Known for its low tooling cost and moderate equipment investment, thermoforming is most economical where production volumes are 10,000 parts per year or less. It allows for great design flexibility, and serves as a practical means for prototyping and pre-production trialing of injection molded applications.

## PRODUCT GUIDE: FORMABILITY

TUFFAK product	Vacuum forming	Drape forming	Line bending
GP	*	*	*
DX-NR	*	*	*
FC	-	*	-
FI	*	*	*
LF	*	*	*
LD	*	*	*
Lumen XT	*	*	*
OP	*	*	*
NR	*	*	*
SL	*	*	*
SK	*	*	*
UV	*	*	*

## Pre-drying TUFFAK sheet

Prior to thermoforming, TUFFAK sheet must be pre-dried to prevent its physical properties from being compromised. Without pre-drying, the high processing temperatures may vaporize the small amount of moisture absorbed in the polycarbonate, causing air bubbles or voids in the thermoformed part.

Pre-dry TUFFAK at 250°F in an air circulating oven equipped with a vent to properly discharge any moisture removed from the sheet. Drying at lower temperatures requires a longer time to thoroughly dry the sheet.


Remove the protective masking from the sheet prior to pre-drying, and hang or rack in the oven with a 1-inch separation to allow for adequate air exposure. Note: sheets stacked without air spacing will not dry. While properly dried TUFFAK sheets will remain dry for approximately eight hours (or less in humid climates and conditions), Plaskolite recommends that sheets be processed as soon as possible upon removal from the oven.

## Registration or distortion thermoforming

Registration forming, also referred to as distortion thermoforming, is the process of taking a distorted printed plastic sheet and vacuum forming the image or picture over the thermoformed mold. This allows the initial distorted image to appear in corresponding areas of mold resulting in a non-distorted, three-dimensional image.

## Drying times/hours

Gauge	250°F	180°F
0.093"	4	8
0.118"	4	14
0.177"	12	30
0.236"	24	50



# Thermoforming



## Forming equipment

When setting up the thermoformer, ensure there is adequate clearance between the clamping frame and mold to allow for deep sheet sag. Optimize the platen speed and clamp frame to maximize the processing rate.


Recommended heater elements include ceramic, quartz and halogen. Calrods and nichrome elements can also be used, but typically do not perform as well for heating control. The most efficient thermoforming machines have both top and bottom heater banks for heating polycarbonate sheet. One-sided heating limits forming method options, and tends to overheat the sheet surface and lengthen cycle times. Zone heating allows different banks of heating coils to be controlled separately to produce even heating. Unbalanced heating can lead to a non-uniform temperature profile in the sheet and is evident by uneven sag of the sheet.

The thermoformer's reserve vacuum tank must be of sufficient size, with a pump capable of generating and maintaining a vacuum of 20-inches Hg pressure throughout the thermoforming cycle.

## Forming techniques


### Vacuum forming

Selection of a female tool versus a male tool depends on the application and is most often determined by the part's appearance or the importance of its fit or assembly. Female tooling is used where the 'outside' part geometry is more important than the surface finish. Male tools are for applications needing 'inside' geometry detail and a blemish-free part surface. Make note that any blemish on the tool (male or female) will result in an imperfection on the part.




### Pressure forming

Pressure forming uses compressed air (up to 100 psi) to force the sheet into the mold. It allows for greater part definition and dimensional control. It also achieves more mold surface detail than other methods for applications that require texturing or lettering, etc.



### Plug-assisted forming

Plug-assisted forming prevents excessive thinning of material in deep-mold cavities. A plug-assisted formed part has more uniform thickness in the walls than a part produced by typical, single-stage vacuum forming.




# Thermoforming



## Twin sheet forming

Twin sheet forming uses two sheets of plastic and two female molds in a single clamp frame setup. A blow pin is inserted between the sheets, and pumps hot air between them to prevent sticking as they soften and sag. This process requires a two-side heater bank. Twin sheet forming is ideally suited to hollow parts with sealed edges, and parts made of two different materials.



## Vacuum forming heating cycle

The target sheet temperature for vacuum forming TUFFAK is between 340°F to 415°F, depending on gauge. The temperature profile of the sheet will define the resulting sag in the sheet. Maintaining the sag depth and shape provides a visual indicator for forming consistency.

### TECH TIP:

Heating from top and bottom shortens cycle time.

### Forming guidelines

#### Sheet temperature

Typical	340°F - 415°F
Optimum	350°F - 375°F

#### Metal mold temperature


210°F - 250°F

## Characteristics of thermoforming polycarbonate


While TUFFAK sheet forming characteristics are different than other thermoplastic sheet materials, it outperforms them in production efficiency due to its short heating times, and rapid forming and cooling cycles.

### Important reminders for thermoforming TUFFAK

- » Thermoforming temperature is relatively narrow: 340°F - 415°F
- » Polycarbonate has a glass transition temperature of 298°F. Above 311°F it begins to soften rapidly.
- » If TUFFAK is not pre-dried, vaporizing moisture absorbed in the sheet can cause air bubbles
- » Polycarbonate cools rapidly. Platen movement and clamp frame travel must operate at appropriate rates without delay.



## Sheet sag at forming temperature



# Thermoforming




## Molds

Extremely durable and higher quality than their lower cost counterparts, aluminum molds are ideal for high volume and recurring production programs. However, for limited or small run volumes, less expensive mold materials like epoxy, fiberglass and wood may be more economical choices.

Note: Aluminum tools require internal heating to maintain a surface temperature of 210°F - 250°F.

## Mold design

**Mold shrinkage:** Molds require oversizing in their design to compensate for part shrinkage due to cooling. TUFFAK sheet shrinkage is 0.005 - 0.007" per inch.



**Draft Angles:** Draft angles greater than 5° allow for easier removal of the part from the mold.

**Radii and Fillets:** Use generous radii wherever possible. The radius minimum should be equal to or greater than the starting material thickness, as this minimizes the thinning of the sheet, improves part rigidity and avoids creating a stress riser point. On female tooling, use corner fillets.

**Vacuum Holes:** To form sheet rapidly and allow for fast air evacuation, make several holes with small diameters. A 0.030-inch diameter hole is usually small enough unless the part's wall thickness is less than 0.030". In female molds, use air evacuation holes at all deep draw areas, especially around the mold perimeter where the sheet draws last.

## Tips on mold design

- » In both male and female tooling, keep the diameter of the drilled holes no larger than the thinnest wall section to avoid marking the sheet. Additionally, in female tooling, design long thin slots for air evacuation.
- » Vapor hone or sand blast metal tools for a uniform surface finish.
- » A highly-polished mold surface is not recommended as it causes sticking and air pockets.
- » The radius minimum should be equal to the sheet's original thickness to relieve stress riser points.
- » Preheat mold. Cold molds can cause surface defects, warping and elevate internal stress in parts.
- » If mold temperature becomes too high during thermoforming, TUFFAK sheet can stick to the mold. Control mold temperature between 210°F and 250°F.


## Free forming

Free blown billow forming (as shown below) is a process used for making dome shapes. Apart from the mold, the procedures and equipment are the same as vacuum forming. Billow forming can be done with compressed air or vacuum.


### Procedure:

1. Pre-dry TUFFAK sheet following recommendations
2. Preheat clamps and tooling to 240-250°F
3. Place sheet in clamping frame of thermoformer
4. Heat sheet until uniform sag forms (340-375°F)
5. Remove heat source
6. Lower pressure box to seal air supply pressure
7. Apply high air pressure initially. As dome takes shape, reduce air pressure
8. When overall height is achieved, maintain positive air pressure until part cools
9. Be sure air source is properly filtered and uniformly dispersed for even formation of dome
10. Utilize electric eye designs or micro switches for height control and consistency
11. Remove and trim part

## Blown dome forming



## Drawn dome forming



## TECH TIP:

Utilize an electronic eye to control height consistency.

# Thermoforming




## Drape forming

Drape forming requires a felt covered wood tool for making a single radius of curvature parts, or designs of slight contours. Face shields and recreational vehicle windscreens are examples of parts made by this method. The sheet is typically heated on an oven shelf or other means of supporting sheet.

### Procedure:

1. Pre-drying TUFFAK sheet is not typically required in drape forming
2. High quality, reproducible forming requires consistent orientation in handling and cutting (top versus bottom), as well as extrusion direction. Do not flip or rotate sheets.
3. Heat oven at 320°F-325°F
4. Locate the oven shelf at the midpoint of the oven for optimum heat balance. Place a felt covered piece of plywood or other flat rigid, heat-resistant sheet on the oven rack or on a portable oven dolly. Be sure to use a fabric cover to protect the sheet from scratches.
5. Bring TUFFAK sheet to forming temperature in the oven at 320-325°F. Depending on gauge, this may take several minutes. For example, 0.118" gauge sheet takes approximately 3-5 minutes.
6. Manually remove the heated sheet from the oven, and immediately position it over the felt covered mold.
7. Apply pressure at the edges of the sheet to help the sheet take the form of the mold or use matched molds (clamshell molds). Cooling takes about 30-60 seconds.
8. Always wear thermal gloves when handling hot sheet, holding the material by its edges.



Typical representation of thermoformed part



## Line bending or strip heating

Line bending, also referred to as strip heating, is a technique for producing linear bends. Generally, pre-drying is not required for line bending TUFFAK sheet gauges up to 0.177". For thicker sheets, back routing or V-grooving along the bend line is recommended.


### Procedure:

1. Remove protective masking in bend area
2. Regulate heating element to 340°F - 365°F
3. Place sheet over heating element at bend area
4. Allow heat to soften material. The amount of time depends on gauge
5. Remove sheet and make desired bend on a felt covered fixture
6. Bend immediately as polycarbonate cools quickly
7. Allow part to cool on the fixture until set up - about 30 seconds

**Note:** Some bends may require a degree of over-bend to achieve desired angle.

## TECH TIPS:

- » Line bending works best for lengths of 24" or shorter. Longer dimensions require preheating the entire piece to 200°F first to prevent warping.
- » For best results with gauges greater than 0.177", use two-side heating, or turn the part frequently when using a one-side heater. This helps with even heat penetration, preventing moisture bubbling.
- » Additionally, for gauges greater than 0.177", back route or V-groove with a 1/16-inch radius to heat cross section. Again, this will help avoid moisture bubbling, while still creating a sharp angle.





# Troubleshooting Guide

# Troubleshooting guide

Society of Plastics Engineers



Description of Problem	Possible Causes	Possible Corrective Action
<b>Bubbles in formed parts</b>	<ul style="list-style-type: none"><li>Excessive moisture</li><li>Heating sheet too rapidly</li><li>Uneven sheet heating</li></ul>	<ul style="list-style-type: none"><li>Pre-dry sheet as recommended</li><li>Preheat sheet</li><li>Heat sheet on both sides</li><li>Protect sheet from moisture until ready to use</li><li>Lower heater temperature</li><li>Increase distance between heater(s) and sheet</li><li>Blow air across the sheet's surface during heating</li></ul>
<b>Crazed or brittle parts</b>	<ul style="list-style-type: none"><li>Mold too cold</li><li>Incompatible mold lubricant</li></ul>	<ul style="list-style-type: none"><li>Increase mold temperature</li><li>Change mold lubricant</li></ul>
<b>Warped parts</b>	<ul style="list-style-type: none"><li>Mold too cold</li><li>Clamp frames too cold</li><li>Removing part too soon</li><li>Overheated part</li><li>Uneven part cooling</li><li>Poor material distribution</li><li>Poor mold design</li><li>Poor part design</li></ul>	<ul style="list-style-type: none"><li>Preheat mold</li><li>Preheat clamp frames</li><li>Increase cooling cycle time</li><li>Use fans to help cool part</li><li>Decrease mold temperature</li><li>Add more coolant channels or tubing to mold</li><li>Check for plugged water flow</li><li>For deep drawing, use pre-stretching or plug assist</li><li>Check for uneven sheet heating</li><li>Add vacuum holes</li><li>Add moat to mold at trim line</li><li>Check for plugged vacuum holes</li><li>Break up large flat surfaces with ribs where practical</li><li>Re-design with tapers or fillets</li></ul>
<b>Texture washout and gloss increase</b>	<ul style="list-style-type: none"><li>Forming temperature too high</li><li>Improper heating technique</li></ul>	<ul style="list-style-type: none"><li>Reduce heater temperature</li><li>Decrease heater cycle time</li><li>Heat sheets from smooth side; keep texture side cool</li><li>Pre-coat texture with strippable mask</li></ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Non-uniform drape</b>	<ul style="list-style-type: none"> <li>Uneven sheet heating</li> </ul>	<ul style="list-style-type: none"> <li>Check heater output and adjust</li> <li>Use selective screening or shading to control heating</li> <li>Check for cold air drafts in heating station</li> </ul>
<b>Incomplete forming of part, poor detail</b>	<ul style="list-style-type: none"> <li>Sheet too cold</li> </ul>	<ul style="list-style-type: none"> <li>Increase heating time</li> <li>Increase heater temperature</li> <li>Increase watt density</li> <li>Check for heating uniformity</li> </ul>
	<ul style="list-style-type: none"> <li>Cold clamping frame</li> </ul>	<ul style="list-style-type: none"> <li>Preheat clamping frame</li> </ul>
	<ul style="list-style-type: none"> <li>Insufficient vacuum</li> </ul>	<ul style="list-style-type: none"> <li>Check for clogged vacuum holes</li> <li>Check for proper location of vacuum holes</li> <li>Increase number of vacuum holes</li> <li>Increase size of vacuum holes</li> <li>Check vacuum pump</li> <li>Check vacuum system for leaks</li> </ul>
	<ul style="list-style-type: none"> <li>Vacuum not drawn fast enough</li> </ul>	<ul style="list-style-type: none"> <li>Where possible, use vacuum slots instead of holes</li> <li>Increase size of vacuum holes</li> <li>Increase vacuum surge and/or pump capacity</li> <li>Increase size of vacuum line and valves; avoid bends and tee-elbow connections</li> </ul>
	<ul style="list-style-type: none"> <li>Part draw ratio too large</li> </ul>	<ul style="list-style-type: none"> <li>Check for vacuum system for leaks</li> </ul>
	<ul style="list-style-type: none"> <li>Insufficient pressure</li> </ul>	<ul style="list-style-type: none"> <li>Increase vacuum capacity</li> <li>Add plug, pressure, or frame assist</li> <li>Increase air pressure on side of part opposite mold surface, if mold can withstand this force</li> <li>Use frame assist</li> <li>Use plug, silicone, slab rubber, or other pressure assist</li> <li>Increase pump capacity</li> </ul>
	<ul style="list-style-type: none"> <li>Poor mold design</li> </ul>	<ul style="list-style-type: none"> <li>Add vacuum holes</li> <li>Check for good seal between clamp frame and vacuum box</li> </ul>
<b>Scorched sheet</b>	<ul style="list-style-type: none"> <li>Top or bottom surface too hot</li> </ul>	<ul style="list-style-type: none"> <li>Decrease heating cycle time</li> <li>Decrease heater temperature</li> </ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Poor surface finish</b>	<ul style="list-style-type: none"> <li>• Mold surface too rough</li> </ul>	<ul style="list-style-type: none"> <li>• Draw-polish mold or use mold material better suited to mold service requirements</li> </ul>
	<ul style="list-style-type: none"> <li>• Mold mark-off</li> </ul>	<ul style="list-style-type: none"> <li>• Use powdered mold lubricant sparingly</li> </ul>
	<ul style="list-style-type: none"> <li>• Draft angle too shallow</li> </ul>	<ul style="list-style-type: none"> <li>• Increase draft angle</li> </ul>
	<ul style="list-style-type: none"> <li>• Air entrapment over smooth mold surface</li> </ul>	<ul style="list-style-type: none"> <li>• Grit-blast mold surface</li> <li>• Add vacuum holes in affected area</li> </ul>
	<ul style="list-style-type: none"> <li>• Insufficient vacuum</li> </ul>	<ul style="list-style-type: none"> <li>• Add vacuum holes</li> <li>• Check for proper location of vacuum holes</li> <li>• Check vacuum system for leaks</li> <li>• Check for plugged vacuum holes</li> </ul>
	<ul style="list-style-type: none"> <li>• Mold too hot</li> </ul>	<ul style="list-style-type: none"> <li>• Decrease mold temperature</li> </ul>
	<ul style="list-style-type: none"> <li>• Mold too cold</li> </ul>	<ul style="list-style-type: none"> <li>• Increase mold temperature</li> </ul>
	<ul style="list-style-type: none"> <li>• Dirty sheet</li> </ul>	<ul style="list-style-type: none"> <li>• Clean sheet with deionizing airgun</li> </ul>
	<ul style="list-style-type: none"> <li>• Dirty mold</li> </ul>	<ul style="list-style-type: none"> <li>• Clean mold with deionizing airgun</li> </ul>
	<ul style="list-style-type: none"> <li>• Dust in atmosphere</li> </ul>	<ul style="list-style-type: none"> <li>• Clean thermoforming area</li> <li>• Isolate thermoforming area and filter air</li> </ul>
	<ul style="list-style-type: none"> <li>• Scratched sheet</li> </ul>	<ul style="list-style-type: none"> <li>• Polish sheet</li> </ul>
<b>Loss of color</b>	<ul style="list-style-type: none"> <li>• Overdrawn sheet (Part too thin)</li> </ul>	<ul style="list-style-type: none"> <li>• Increase sheet gauge</li> <li>• Increase sheet temperature</li> <li>• Use pre-draw</li> <li>• Use plug assist for deep-draw parts</li> </ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Chill marks or mark-off</b>	<ul style="list-style-type: none"> <li>Mold temperature too low; stretching stops when sheet meets cold mold or plug</li> <li>Insufficient draft angle and radii</li> <li>Plug temperature too low</li> <li>Sheet too hot</li> </ul>	<ul style="list-style-type: none"> <li>Increase mold temperature</li> <li>Increase draft angles and mold radii</li> <li>Increase plug temperature</li> <li>Use wood plug assist</li> <li>Cover plug with cotton flannel or felt</li> <li>Reduce heater temperature</li> <li>Heat more slowly</li> <li>Use fans to reduce the surface of hot sheet slightly before forming</li> </ul>
<b>Nipples on mold side of formed part</b>	<ul style="list-style-type: none"> <li>Vacuum holes too large</li> <li>Dust on mold or sheet</li> <li>Mold too cold</li> <li>Mold surface too smooth</li> <li>Vacuum rate too high</li> <li>Sheet too hot</li> </ul>	<ul style="list-style-type: none"> <li>Decrease hole size</li> <li>Clean mold and sheet with deionizing air gun</li> <li>Increase mold temperature</li> <li>Draw-sand mold surface with medium-grit paper</li> <li>Place small orifice over main vacuum hole</li> <li>Decrease heating cycle time</li> <li>Decrease heater temperature</li> </ul>
<b>Webbing, bridging, or wrinkling</b>	<ul style="list-style-type: none"> <li>Sheet too hot in center</li> <li>Sheet too cold in webbing area</li> <li>Mold too cold</li> <li>Vacuum rate too fast</li> <li>Insufficient vacuum</li> </ul>	<ul style="list-style-type: none"> <li>Screen center of sheet, allowing edges to heat first; use taller vacuum box to provide more pull in area</li> <li>Decrease heating cycle time</li> <li>Decrease heater temperature</li> <li>Use pattern heating</li> <li>Increase bellow height</li> <li>Increase mold temperature</li> <li>Slow down vacuum rate</li> <li>Use smaller vacuum holes</li> <li>Restrict main vacuum line</li> <li>Check vacuum system for leaks</li> <li>Increase number of vacuum holes or slots</li> <li>Check for clogged vacuum holes</li> <li>Check for proper location of vacuum holes</li> <li>Increase size of vacuum holes</li> </ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Webbing, bridging, or wrinkling – Cont.</b>	<ul style="list-style-type: none"> <li>Draw ratio too great in area of mold, or poor mold design or layout</li> <li>Blanks too large for mold</li> <li>Uneven cooling due to slow drape speed</li> </ul>	<ul style="list-style-type: none"> <li>Redesign mold</li> <li>Use plug or ring mechanical assist</li> <li>Use female mold instead of male mold</li> <li>Add take-up blocks to pull out wrinkles</li> <li>Increase draft and radii where possible</li> <li>Increase space between multiple articles</li> <li>Speed up assist and/or mold travel</li> </ul>
<b>Insufficient draw-down</b>	<ul style="list-style-type: none"> <li>Improper sheet heating</li> <li>Insufficient vacuum</li> </ul>	<ul style="list-style-type: none"> <li>Redesign grid, plug, or ring assists</li> <li>Leave minimum of material around mold</li> <li>Drape at higher speed</li> </ul>
<b>Poor wall thickness distribution and excessive thinning in some areas</b>	<ul style="list-style-type: none"> <li>Uneven heating</li> <li>Improper forming technique</li> </ul>	<ul style="list-style-type: none"> <li>Increase heating time and temperature</li> <li>Check vacuum system for leaks</li> <li>Check uniformity of heater output</li> <li>Use screening or shading to control heating</li> <li>Check for drafts or air current in heating station</li> </ul>
	<ul style="list-style-type: none"> <li>Excessive sag</li> <li>Cold mold</li> <li>Sheet pulls from rails</li> </ul>	<ul style="list-style-type: none"> <li>Use billow or snap-back forming method</li> <li>Reduce time delay between pre-stretch and mold drawing</li> <li>Control height</li> <li>Reduce sheet temperature</li> <li>Use pattern heating</li> <li>Increase mold temperature</li> <li>Check for uniform mold heating</li> <li>Check temperature control system for scale or plugging</li> <li>Air-cool rails prior to heating</li> <li>Move rails in to grasp more sheet</li> <li>Use drag bands at rail edge</li> </ul>
	<ul style="list-style-type: none"> <li>Sheet slips from frame</li> </ul>	<ul style="list-style-type: none"> <li>Adjust frame alignment</li> <li>Increase frame clamp pressure</li> <li>If retainer springs are used, change to high-temper springs</li> <li>Pre-heat frames prior to inserting sheet</li> <li>Check heaters around clamp area for proper operation</li> <li>Screen or shade center of sheet to allow more heat at perimeter</li> </ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Shiny streaks on part</b>	<ul style="list-style-type: none"><li>Sheet too hot in spots</li></ul>	<ul style="list-style-type: none"><li>Lower heater temperature in overheated area</li><li>Use screening or shading to control heating</li><li>Decrease heating cycle time</li><li>Increase distance between heater and sheet</li></ul>
<b>Excessive shrinkage or distortion of part after removing from mold</b>	<ul style="list-style-type: none"><li>Part not adequately cooled</li><li>Mold too hot</li></ul>	<ul style="list-style-type: none"><li>Increase cooling cycle time</li><li>Use cooling fixtures</li><li>Increase capacity of cooling system</li><li>Use fan or vapor spray mist to cool part faster on mold</li><li>Reduce mold temperature</li><li>Increase mold coolant flow rate</li></ul>
<b>Corners too thin in deep draw</b>	<ul style="list-style-type: none"><li>Uncontrolled material distribution</li><li>Sheet too thin</li><li>Sheet temperature too high at corners</li><li>Mold temperature not uniform</li><li>Drape speed too fast</li></ul>	<ul style="list-style-type: none"><li>Consider other techniques such as billow-up, plug assist, etc.</li><li>Use heavier-gauge sheet</li><li>Use screening or shading to control heating pattern</li><li>Adjust temperature control system for uniformity</li><li>Check operation of mold heating system</li><li>Reduce drape speed</li></ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Difficult part removal</b>	<ul style="list-style-type: none"> <li>Part or female mold temperature too hot</li> <li>Male mold too cold, part sticking</li> <li>Male mold too hot, causing part distortion</li> <li>Insufficient mold draft</li> <li>Ejection pressure too low</li> <li>Mold undercuts</li> <li>Wood Mold</li> <li>Rough mold surface</li> </ul>	<ul style="list-style-type: none"> <li>Increase cooling cycle time</li> <li>Decrease mold temperature</li> <li>Increase mold temperature</li> <li>Decrease mold temperature</li> <li>Increase taper/draft</li> <li>Use female mold</li> <li>Remove part from mold as soon as possible</li> <li>Add air holes</li> <li>Increase injection pressure</li> <li>Use powdered mold release</li> <li>Use stripping frame</li> <li>Increase air-eject air pressure</li> <li>Remove part from mold as soon as possible</li> <li>Spray mold surface with a compatible mold release agent</li> <li>Polish corners or entire mold surface</li> <li>Use mold-release agent</li> <li>Use PTFE spray</li> </ul>
<b>Loss of vacuum seal</b>	<ul style="list-style-type: none"> <li>Cold clamp frames</li> <li>Improper spacing between clamp frames and vacuum box</li> </ul>	<ul style="list-style-type: none"> <li>Preheat clamp frames</li> <li>Adjust space between clamps and vacuum box to between 0.50 and 0.750 in. (13 and 19 mm)</li> </ul>
<b>Sheet sticking to plug</b>	<ul style="list-style-type: none"> <li>Plug temperature too hot</li> <li>Wood plug assist</li> </ul>	<ul style="list-style-type: none"> <li>Decrease plug temperature</li> <li>Use mold release agent on plug</li> <li>Apply a PTFE coating</li> <li>Cover plug with felt cloth or cotton flannel</li> <li>Cover plug with felt cloth or cotton flannel</li> <li>Use mold release agent on plug</li> <li>Apply a permanent PTFE coating to surface of plug</li> </ul>
<b>Tearing of sheet during forming</b>	<ul style="list-style-type: none"> <li>Mold design</li> <li>Sheet too hot <ul style="list-style-type: none"> <li>Decrease heater temperature</li> <li>Check sheet for uniform heating</li> <li>Preheat sheet</li> </ul> </li> <li>Sheet too cold (usually thinner gauges) <ul style="list-style-type: none"> <li>Increase heater temperature</li> <li>Check sheet for uniform heating</li> <li>Preheat sheet</li> </ul> </li> </ul>	<ul style="list-style-type: none"> <li>Increase corner radius</li> <li>Decrease heating cycle time</li> <li>Increase heating cycle time</li> </ul>

# Troubleshooting guide



Description of Problem	Possible Causes	Possible Corrective Action
<b>Tearing of sheet during forming - Cont.</b>	<ul style="list-style-type: none"> <li>Poor material distribution</li> <li>Pre-stretch too large</li> </ul>	<ul style="list-style-type: none"> <li>Check sheet for variations in gauge</li> <li>Check sheet for uneven heating</li> <li>Reduce billow blowing time</li> <li>Reduce billow temperature</li> </ul>
<b>Cracking of part during service</b>	<ul style="list-style-type: none"> <li>Stress concentration</li> <li>Poor part or mold design</li> <li>Sheet gauge too thin for draw</li> <li>Uneven sheet temperature</li> </ul>	<ul style="list-style-type: none"> <li>Increase fillets</li> <li>Increase sheet temperature</li> <li>Be sure part is completely formed before removing from mold</li> <li>Use proper forming temperature and cooling rate for deep-draw parts</li> <li>Increase mold temperature</li> <li>Re-evaluate design</li> <li>Increase sheet gauge</li> <li>Use screening or shading to control heating pattern</li> </ul>
<b>Poor embossing detail</b>	<ul style="list-style-type: none"> <li>Embossing depth too shallow</li> <li>Drawing not uniform</li> </ul>	<ul style="list-style-type: none"> <li>Increase depth of embossing pattern</li> <li>Use screening or shading to control heating pattern</li> <li>Use plug assist and/or billow to pre-stretch sheet</li> </ul>
<b>Excessive sheet sag</b>	<ul style="list-style-type: none"> <li>Sheet too hot</li> <li>Sheet area too large</li> </ul>	<ul style="list-style-type: none"> <li>Decrease heating cycle time</li> <li>Decrease heater temperature</li> <li>Use screening or shading to control heating, particularly in the center of the sheet.</li> </ul>
<b>Varying sag levels among sheets</b>	<ul style="list-style-type: none"> <li>Sheet-to-sheet temperature variation</li> </ul>	<ul style="list-style-type: none"> <li>Check for cold air drafts in heating station</li> </ul>
<b>Non-uniform billow</b>	<ul style="list-style-type: none"> <li>Uncontrolled sheet heating</li> <li>Non-uniform die pressure within billow</li> </ul>	<ul style="list-style-type: none"> <li>Check heaters for proper operation</li> <li>Use screening or shading to control heating</li> <li>Check for cold air drafts in heating station</li> <li>Check air pressure system for leaks</li> <li>Check seal between sheet and billow box</li> <li>Redirect incoming air to billow box</li> </ul>

Brake Bending,  
Cold Forming,  
Annealing


# Brake bending

## Brake bending

TUFFAK polycarbonate sheet up to 0.177" thick can be brake bent up to 90° angles. For gauges thicker than 0.177", strip heat bending is recommended to prevent potential cracks or breakage. Strip heat bending should also be used for all flame-resistant sheet grades.

### TECH TIPS:

- » Perform the bending operation quickly
- » To attain the desired angle, some degree of over-bend is required
- » Do not brake bend flame retardant grades due to possibility of cracking
- » For best results with gauges greater than 0.177", use two-side heating, or turn the part frequently when using a one-side heater. This helps with even heat penetration, preventing moisture bubbling.
- » Additionally, for gauges greater than 0.177", back route or V-groove with a 1/16-inch radius to heat cross section. Again, this will help avoid moisture bubbling, while still creating a sharp angle.



# Annealing

## Batch oven method

Annealing is a way of relieving internal stresses in thermoplastic parts caused by thermoforming or fabrication. The polycarbonate sheet is thermal conditioned at an elevated temperature over a specified time period and then cooled slowly. Through annealing, potential dimensional instability of a part, such as warp, is also reduced.

While annealing is effective for reducing stresses, it is time-consuming and may not be economical or practical for all situations. Also, extended heat histories can affect the physical properties of plastics. If you have questions or concerns regarding annealing, contact your Plaskolite representative, or the Technical Service Group.


# Cold forming

## Cold forming

TUFFAK sheet may be cold-formed, bent into place without heating, to a radius based on the sheet thickness. As a guideline, the minimum cold forming radius is equal to 100 times the thickness:  $(R = T \times 100)$ .

### Cold forming radius guide – inch

Sheet thickness	Minimum radius
0.118	12
0.177	18
0.236	24
0.370	37



## TUFFAK cold forming product guide

Cold formable	Not cold formable
GP	15
DX-NR	AR
FC	Hygard®
FI	NR-C
LF	
LD	
Lumen XT	
NR	
OP	
SL	
SK	
UV	

## Annealing procedure:

1. Prior to heating, support or fixture the part to the desired geometry using low thermal conductivity framing (e.g., wood)
2. Slowly heat oven, fixture and part at the same time to 250°F
3. Hold at 250°F for 15 minutes per 0.125" sheet thickness
4. Turn off heater, blower remains on, starting the cool-down cycle
5. Remove part from oven, remove the part from the fixture



## Bonding Applications



# Bonding Applications



## Solvent bonding

Solvent bonding joins one plastic to itself or another type of plastic that dissolves in the same solvent. Typically, this process involves treating the bonding area with the *minimum* amount of solvent needed to soften the surfaces and then clamping the parts together until they bond.

Methylene chloride or ethylene dichloride bonds TUFFAK sheet to itself. Methylene chloride's fast evaporation rate helps to prevent solvent vapor entrapment for simple assemblies. For complex assemblies that require more curing time, use ethylene dichloride. A 60/40 mixture of methylene chloride and ethylene dichloride will allow for longer a time to assemble parts than pure methylene chloride.

**Expect brittleness and reduced impact strength at the bonded joints.**

**Note: Wear proper protective equipment when working with chemicals. Adequate ventilation is essential.**

**Review Safety Data Sheet from product manufacturer and control exposure according to OSHA guidelines.**

## Bonding procedure

1. For optimum bonding, confirm the parts mate flush. This helps to ensure uniform pressure distribution across the entire bond area.
2. Clean joint surfaces with isopropyl alcohol.
3. Use fresh solvent.
4. For best results, avoid using excessive solvent - it causes bubbling and "squeeze-out," which decreases bond strength.
5. Apply a thin bead of solvent using a needle applicator; the capillary action will pull the solvent into the joint interface.
6. For large parts, it may be easier to use a shallow pan containing enough solvent to cover the edge of the bonding part.
7. Dip part into pan, wetting its edge.
8. Transfer onto mating part.
9. Apply pressure to the mating parts.
10. Hold fixture for a minimum of 60 seconds.
11. The bonded part is now safe to handle.

## TECH TIPS:

- » A fully cured joint requires 24-48 hours drying time
- » Always cure parts in a well-ventilated area; never in an enclosed space. Trapped methylene chloride vapors chemically attack polycarbonate, reducing its physical properties.
- » A 5-10% solution of polycarbonate shavings dissolved in methylene chloride helps to produce a smooth, filled joint and improves strength. For critical applications requiring more durability consider an adhesive product.

## Avoid whitening of bond

- » Use fresh solvent whenever possible. Once a container is opened, the solvent can absorb moisture from the air over time. Wet solvent can cause a cloudy bond.
- » Fabricate in a climate controlled area with low relative humidity.
- » Add 10% glacial acetic acid to a container of previously opened solvent to help reduce whitening.
- » Add 5-10% polycarbonate shavings to the solvent to help slow cure time and reduce whitening.

## Adhesive bonding


Adhesive bonding systems are among the most robust for joining plastic parts to parts made of the same plastic, different plastics or non-plastic materials. Generally, adhesives produce more consistent and predictable results in joints requiring strength and durability than other joining methods.

### Consider the following when selecting an adhesive bonding material:

- » Chemical compatibility with TUFFAK sheet
- » Flexibility or rigidity requirements
- » Load bearing force
- » Environmental condition and temperature requirements
- » Aesthetics

### General characterizations of different adhesive systems:

- » In general, urethane and epoxy adhesives impart excellent bond strength.
- » UV-cured adhesives, attractive for curing in seconds, provide high bond strength.
- » Silicone adhesives have flexible, strong bonds.
- » Foamed adhesive tapes are known for strength and durable performance.
- » Hot melts provide quick set times where high bond strength is not required.
- » Use care in selecting adhesives, as some can be aggressive toward TUFFAK sheet.



# Bonding Applications



## Adhesion selection guide

Product	Description	Bond type
Methylene chloride	Solvent	High tensile strength, low impact resistance
Urethane	Polymer base	Structural bond, fatigue resistant, limited flexibility and UV resistance
Epoxy	Polymer; 1 and 2 component	Structural bond, heat and chemical resistant, limited flexibility, absorbs moisture
Silicone	Silicone	Flexible, strong bond, heat, chemical, environmentally resistant
Adhesive tape	Acrylic adhesive foam-backed, films	Flexible, structural bond, for non-aesthetic uses
Hot melts	Polymer	Fast set, versatile, range of bond strengths

## Selected product web links

Solvent, hardware store, chemical suppliers

**SOLVENT CEMENT:**

[http://es.ipscorp.com/pdf/assembly/AssemblyAdhesive\\_Product\\_Selection%20Guide\\_Jan08.pdf](http://es.ipscorp.com/pdf/assembly/AssemblyAdhesive_Product_Selection%20Guide_Jan08.pdf)

**URETHANE:** <http://es.ipscorp.com/assembly/polycarbonate>;

**EPOXY:** <http://www.masterbond.com/lp/performance-properties-and-common-applications>

**SILICONE:** <http://www.tremcosealants.com/products/proglaze-ssg.aspx>

**ADHESIVE TAPE:** [http://solutions.3m.com/wps/portal/3M/en\\_US/Adhesives/Tapes/Brands/3M-VHB-Tape/](http://solutions.3m.com/wps/portal/3M/en_US/Adhesives/Tapes/Brands/3M-VHB-Tape/)

**HOT MELT:** <http://www.bostik-us.com/our-brands/thermogrip>



# Mechanical Fastening

# Mechanical Fastening




## Mechanical fasteners




Due to their low cost and reliability, screws, bolts and rivets are common joining methods. Common practices and selection criteria are discussed within this section.

### Common head styles of screws and bolts

Pay special attention to the fastener's head. Use bolt and screw heads that have a flat underside, called "pan" or "round" head. This bolt design imparts lower compressive stresses on the material. Conical heads, called flat or oval heads, produce undesirable tensile and hoop stresses and should be avoided.



### Fastening with bolts, nuts, and washers



### Fastening with self-tapping screws

Use thread-cutting screws, which cut away material from a pre-drilled hole to form a mating thread and result in better long-term performance. Note the radial and hoop stresses imparted to the part by thread-cutting screws are lower after installation vs. thread-forming screws. Typically, thread-cutting screws are classified as ANSI BT (Type 25), ANSI T (Type 23). Thread-cutting screws may not be appropriate in all applications and environments. Cracks around the screw hole may form under conditions where the polycarbonate expands and contracts due to temperature variations.




Hi-Lo is a trademark of ITW Shakeproof

### Fastening with rivets

Rivets offer a low-cost and simple hardware solution for static parts. Aluminum rivets are preferred over harder materials. Select rivets with large flat heads and three times the shank diameter. Use of washers on the flared end are helpful in distributing loads, but be careful not to over-tighten as it can result in compressive stress and damage to the plastic.

### Four standard rivet heads



Use flat aluminum or hard plastic washers under nuts and fastener heads to evenly distribute the applied force. Their ability to resist over-compression helps to prevent localized stressing of the joining part. Ensure there is sufficient distance between the edge of the fastener's hole and the part's edge: at minimum, two-times the diameter, and twice the part's thickness. Note: Slotted holes require more edge clearance.

#### TECH TIP:

Avoid thread locker products. They are generally incompatible with TUFFAK polycarbonate sheet, causing cracking and crazing.

# Mechanical Fastening



## Joining dissimilar materials





For assemblies constructed of a combination of TUFFAK sheet and metal (two dissimilar materials), it is important to design for thermal movement behavior. When heated, the plastic may buckle, due to its higher thermal expansion rate. Conversely, when cooled, the greater thermal shrinkage of plastic will cause strain-induced stress and may exceed the plastic's working limit. This could lead to part failure.

The figure to the right shows a plastic part fastened to a metal component. As the ambient temperature rises, the plastic will expand more than the metal because the plastic's coefficient of linear thermal expansion is four times higher.

For applications where wide temperature variations exist, use slotted screw holes in the plastic part. When joining plastic and metal parts, do not tighten fasteners to the point where joint friction and compressive loads prevent relative movement. If the fasteners are too tight it negates the effect of the slotted holes.

### Factors to consider when joining plastic and metal parts:

- » The size of the parts to be joined
- » The magnitude of the temperature range
- » The relative thermal expansion coefficients of the materials used in the part



## Coefficient of Linear Thermal Expansion (CLTE) values for materials

Material	CTLE ( $10^5$ in/in/ $^{\circ}$ F)
TUFFAK	3.8
Aluminum	1.3

**Example 1:** Calculate the change in length for a 96 inch part that is constructed at 70° F, but will see operating temperatures up to 120° F

$$\Delta L = (\text{plastic CLTE} - \text{metal CLTE}) * \text{temperature change} * \text{length of part} \quad (0.000038 - 0.000013) * 50 * 96 \dots \dots \Delta L = 0.120 \text{ inches}$$

Therefore, the design has to accommodate a growth of 0.12 inches.

**Example 2:** How much shrinkage will the same part see at -20° F

$$\Delta L = (\text{plastic CLTE} - \text{metal CLTE}) * \text{temperature change} * \text{length of part} \quad (0.000038 - 0.000013) * 90 * 96 \dots \dots \Delta L = 0.216 \text{ inches}$$

Therefore, the design has to accommodate a contraction of 0.216 inches.

# Mechanical Fastening



## Ultrasonic welding

An ultrasonic welder has two primary parts: a horn and a nest. The horn typically presses down on the upper plastic part (of the two to be welded), clamping the two parts together. The nest supports the bottom plastic part to prevent it from moving. The horn is vibrated ultrasonically for a preset time. Friction from mechanical vibrations cause localized heating, resulting in plastic melting at the interface of the two parts. Pressure is then maintained after the vibrations are stopped until the melted plastic cools. Once the plastic has solidified, the clamping pressure is retracted and the two joined parts can be removed from the nest fixture.

The most important feature for a clean, ultrasonically welded joint is for one of the parts (to be welded) be designed with a triangular-shaped energy director. This minimizes the initial contact between parts. During welding, the ultrasonic energy is concentrated at the director tip, melting it and ultimately, joining the interface with molten resin.

Design energy directors with an apex angle from 60 to 90°. Generally, the base width of the energy director should not be more than 20 to 25% of the wall thickness supporting it.


## Troubleshooting

- » Clean the mating surfaces with isopropyl alcohol to remove dust, fingerprints and grime prior to welding.
- » Check to see if the horn is making proper contact to the welding surface. Non-uniform horn contact produces non-uniform weld lines. Carbon paper is useful to confirm uniform contact.
- » Confirm sufficient energy is being supplied into the weld.
- » Increase pressure/clamping force on the parts being welded.
- » Increase the weld time.
- » Increase the amplitude to the horn. Consult equipment suppliers for recommended welding amplitude settings for polycarbonate.

For ultrasonic welding machines, the converter, booster, and a properly maintained weld horn are all key factors for delivering a welding amplitude that produces a repeatable and robust weld joint. Confirm that routine maintenance, daily checks and calibration programs are in place. Set and document minimum energy output for the unit that ensures a reproducible welding joint.

## For optimum welding:

- » The horn, fixture and parts must be aligned properly
- » The stationary part should fit snugly in the nest or fixture
- » The height of the energy director should be approximately 0.020 inch
- » Join parts made of the same resin



## For more information on ultrasonic joining techniques contact:

### Branson Ultrasonics Corp.

<http://www.emersonindustrial.com/en-US/branson/Products/plastic-joining/Pages/default.aspx>

### Dukane Corp. [http://www.dukane.com/us/PPL\\_upa.htm](http://www.dukane.com/us/PPL_upa.htm)

### Forward Technology Industries, Inc. <http://www.forwardtech.com/plastic-assembly>

### Herrmann Ultrasonics, Inc. <http://www.herrmannultrasonics.com/products-plastics.html>

### Ultra Sonic Seal Co. [http://www.ultrasonicseal.com/upa/upa\\_tooling.html](http://www.ultrasonicseal.com/upa/upa_tooling.html)



MINUTEk LX3 Pro

## Finishing

# Finishing



The aesthetics or functionality of TUFFAK sheet can be enhanced through finishing or surface-decorating processes. Painting and screen-printing are typical decorating methods for enhancing a part's visual appeal.

Metallizing is an example of a process that adds functionality, such as electromagnetic shielding. Before decorating with any material, contact the manufacturer to confirm its suitability for use, and compatibility with polycarbonate.

## PRODUCT GUIDE: DECORATION METHOD

TUFFAK Products	Digital Print	Screen Print	Paint	Vinyl	Hot Decorating
AR1 <sup>4</sup>	*	*	*	*	*
GP	*	*	*	*	*
DX-NR <sup>1</sup>	*	*	*	-	*
FC <sup>2</sup>	-	-	-	*	-
FI	*	*	*	*	*
LF	*	*	*	*	*
LD	*	*	*	*	*
Lumen XT <sup>1</sup>	*	*	*	-	*
NR <sup>1</sup>	*	*	*	*	*
NR-C <sup>4</sup>	*	*	*	*	*
OP	*	*	*	*	*
SL	*	*	*	*	*
SK <sup>3</sup>	-	-	*	-	-
UV	*	*	*	*	*

1. Textured surface may interfere with decoration media, requires testing/verification

2. Hard coat surface interferes with adhesion, requires testing/verification

3. Painting prismatic surface will interfere with optical properties, requires testing/verification

4. AR1 and NR-C decorate the non-coated side of the sheet

### Screen printing

TUFFAK sheet can be printed with standard silk screening equipment. Note that screen mesh affects both the amount of ink that is deposited, as well as the resolution of the printed image.

As with all thermoplastics, TUFFAK sheet must be clean and free from surface contaminants prior to screening. Many screen printers use a 50:50 washing solution of water:isopropyl alcohol to clean the surface prior to printing. Be sure to use soft, nonabrasive cloths when cleaning to avoid scratching. Antistatic or ionized air guns also provide a good method for removing lint and dust, as well as static.

After printing, keep sheets separate on a drying rack until ink is dry. DO NOT pack sheets for shipment until inks are completely dry.

### Digital printing

UV cured inks are used in digital printing due to their quick cure times. Historically, a UV Mercury arc lamp has been used as the light source, but newer UV LED curing lamps are now preferred. These bulbs use less electricity, produce less heat, last much longer and do not require a warm-up period. It's important to note however, that the market has reported intermittent adhesion issues when printing on plastic substrates when curing

with UV LED systems. Pretreating the plastic substrate with corona discharge, flame, UV light, solvent wipes, or adhesion promoters has proven successful in overcoming adhesion issues.

For advice on UV LED cure ink applications, contact the Technical Service Group at 800.628.5084.

### Painting

Many commercially available paints are available for TUFFAK sheet. Be sure to use only paints that have been tested by the supplier to be compatible with polycarbonate. As with screen printing, it is important the surface of the TUFFAK sheet be clean and free from surface residuals prior to painting. Many painters use a pre-rinse of 50:50 (water : isopropyl alcohol) to clean the surface. Be sure to dry thoroughly prior to painting. Use a soft, nonabrasive cloth or sponge to avoid scratching. Conventional spray, spray masked, roller coat and brush are common application methods.

### Vinyl decorating

Application of colored vinyl film is a common decoration technique for TUFFAK sheet. Follow the vinyl film manufacturer's directions for product use. Flash drying TUFFAK sheet for at least one hour at 250°F prior to the film application has been shown useful in helping to prevent bubbling or blistering of the film over time.



## Hot stamping

TUFFAK sheet is easily decorated with a single-color image by hot stamping, a process widely used for its convenience, versatility and performance. A heated die fuses the impression made by the stamp to transfer color from the foil carrier to the substrate. The temperature, pressure and dwell time are adjusted based on the type of foil and substrate. Contact equipment and foil manufacturers about processing conditions and products for polycarbonate.

## Heat transfer

Heat transfer decorating also uses a combination of heat, pressure and dwell time to apply preprinted graphics onto a part. Unlike hot stamping, the graphics are preprinted images that can be complex and multicolored. The major advantage of heat transfer decorating over printing or painting is that it is a dry process, making it more environmentally friendly. There are no strong odors associated with the process from volatile chemicals.

## Printing and painting hard coated sheet products

Adhesion of ink and paint to the abrasion resistant coated surface is unreliable and not recommended on TUFFAK 15, TUFFAK AR, TUFFAK NR-C and TUFFAK FC. TUFFAK AR1 is a one-side hard coated sheet that can be printed on the side opposite of the coating, thus allowing for decoration in combination with the weatherable abrasion resistant coating.

## Solvent polishing

In order to improve the look of saw-cut edges, begin by sanding the edges smooth. For smoother, glossy edges, consider solvent polishing with methylene dichloride. To prevent humidity blush

after drying, it may be necessary to add a small amount of glacial acetic acid. Keep in mind that polishing cannot be expected to totally eliminate sand marks from the sheet edge. Solvent polishing is not recommended on laminated products and should only be used on monolithic polycarbonate sheet.

**Note:** Use extreme caution when working with solvents. Adequate ventilation is essential. Control exposure levels according to OSHA guidelines. Obtain Safety Data Sheets from the solvent manufacturer.

## Sanding

The edges of TUFFAK sheet can be sanded using both wet and dry techniques. Of the two, wet sanding produces a smoother finish and is less likely to gum the sandpaper. In both instances, the part will require further finishing such as solvent polishing in order to yield a high gloss appearance.

TUFFAK sheet can also be buffed using a 2-wheel system. The first wheel uses a buffering compound to remove shallow scratches. The second buffering wheel is used for restoring the gloss.

## Jointing-planing

A standard woodworking jointer-planer can be used to finish TUFFAK sheet edges. Blades must be carbide or high-speed steel. Avoid removing too much material in each pass, 1/64" or less normally yields the cleanest edge. Attempting to remove too much material in a single pass results in a rough edge or cracking of the sheet.

If smoother edges are required, wet sanding with fine grit sandpaper is recommended.

## SOURCES

### INK

**ASPA:** [www.screenprinting-aspa.com/inks-for-screen-printing.html](http://www.screenprinting-aspa.com/inks-for-screen-printing.html)

**Ink World:** [www.inkworldmagazine.com/trade-associations](http://www.inkworldmagazine.com/trade-associations)

**NAPIM:** [www.napim.org/printing-inks](http://www.napim.org/printing-inks)

**PNEAC:** [www.pneac.org](http://www.pneac.org)

**SGIA:** [www.sgia.org/printing-imaging](http://www.sgia.org/printing-imaging)

**SignIndustry.com:** [www.signindustry.com/screen/](http://www.signindustry.com/screen/)

### DIGITAL PRINTING

**EFI:** <https://customer.efi.com/support/ccpIndex>

**Radtech:** [www.radtech.org](http://www.radtech.org)

**ScreenWeb:** [www.screenweb.com/bg](http://www.screenweb.com/bg)

**SGIA:** [www.sgia.org/printing-imaging/digital-printing-and-imaging](http://www.sgia.org/printing-imaging/digital-printing-and-imaging)

### FOIL

**FSEA:** [www.fsea.com/quicklinks.asp?columnpick=hotstampingfoil](http://www.fsea.com/quicklinks.asp?columnpick=hotstampingfoil)

### PAINT

**ACA:** <http://paintandcoatingsbuyersguide.com>

**Akzo Nobel Coatings:** [www.akzonobel.com](http://www.akzonobel.com)

**Matthews Paints:** [www.ppg.com/coatings/matthewspaint/pages/default.aspx](http://www.ppg.com/coatings/matthewspaint/pages/default.aspx)

**Naz-Dar Corporation:** [www.nazdar.com](http://www.nazdar.com)

**SignIndustry.com:** [www.signindustry.com/painted](http://www.signindustry.com/painted)



# Glazing Guidelines

DAL GRAUER

S U B S T A T I O N

# Glazing




TUFFAK polycarbonate sheet can be installed using wet (caulking type sealant) or dry (gasket type) glazing systems. TUFFAK sheet can be glazed as a single layer, as two layers for added thermal insulation or over-glazed for increased security to an existing window.

## General recommendations

- » Match the metal framing (typically aluminum or steel) to the application requirements, such as the wind load or ballistics
- » Engage all sheet edges in the frame
- » Ensure the rabbet depth is sufficient for edge engagement, as well as thermal expansion or contraction
- » Use gaskets, sealants and tapes compatible with polycarbonate that have adequate elongation capability; contact the manufacturer of the product if unsure
- » Note that fastening with bolts through the glazing should only be used when unavoidable; the design needs to be reviewed to ensure thermal movement will not be restricted
- » Note that a sash intended for glass is unlikely to have enough rabbet depth, particularly for windows larger than 36 inches in one dimension
- » Use dry glazing with EPDM or neoprene gaskets for large windows (greater than 24 inches); sealants specifically designed with high elongation may also be a consideration
- » Peel back the masking only around the perimeter of the sheet prior to installation to protect from damage. Remove the remaining masking once the installation is complete. Do not leave the masking on the sheet for an extended period.
- » Use isopropyl alcohol or VM&P naphtha and a soft cloth for cleaning during installation
- » Refer to the TUFFAK sheet cleaning guideline for recommended practices and products

## Thermal expansion allowance

The coefficient of linear thermal expansion of TUFFAK sheet is much greater than framing materials, such as aluminum and steel (see table for comparisons). The window design needs to accommodate for adequate expansion room to allow for free movement of the sheet to avoid unsightly sheet bowing and optical distortion. A general guideline is to allow 1/16 inch expansion/contraction per foot of sheet in both the length and width directions.



## Comparative expansion rates

Material	Inch/Inch/°F
TUFFAK	0.0000375
Glass	0.0000050
Aluminum	0.0000129
Steel	0.0000063

## Example calculation rabbet depth for a 48-inch sheet length and 70° temperature change

### Calculation of Expansion/Contraction


$0.0000375 \times \text{sheet dimension inches} \times \text{temperature change}$

48" expansion:  $0.0000375 \times 48 \times 70 \text{ degrees} = 0.13"$

48" contraction:  $0.0000375 \times 48 \times 70 \text{ degrees} = 0.13"$

Rabbet depth:

Edge engagement + Expansion + Contraction  $0.56 + 0.26 = 0.82"$



## Sheet edge engagement, thermal expansion and rabbet depth table

Sheet size	24"	36"	48"	60"
Expansion + Contraction	1/8"	3/16"	1/4"	5/16"
+ Edge engagement	3/8"	1/2"	9/16"	3/4"
= Rabbet depth	1/2"	11/16"	13/16"	1-1/16"

# Glazing









## Wind load

The wind load charts cover a range of sheet sizes and aspect ratios; consult the size closest to the design of interest. Within each chart, the thickness of the sheet is represented in the horizontal axis, and each color line represents a different wind load. The predicted deflection is for a given size window, sheet thickness, and wind load represented in the vertical axis. If a

deflection exceeds 2.5 inches, consider thicker sheet for the application.

### Wind load deflection calculation assumptions:

- » All edges of the sheet are engaged in the frame
- » Dry glazing with 15% gasket compression clamping force allowing for sliding retention



— 10 psf — 20 psf — 30 psf — 40 psf — 50 psf

Design pressure	Hurricane category	MPH
10 PSF	63 MPH	-
20	88	1 74-95
30	108	2 96-110
40	125	3 111-129
50	140	4 130-156

# Glazing




## Basic glazing methods

The following requirements apply for both wet and dry glazing:

- » Measure the rabbet depth of the frame
- » Account for design wind load
- » Confirm edge engagement
- » Address potential expansion and contraction of the glazed dimension
- » Check for compatibility and adhesion of gasket, sealant or tape


## Wet glazing

Wet-glazing is typically limited up to a 36x36 inch size window. Glazing shim tape is used to back the sealant cap bead as shown in the image.



## Dry glazing


For dry glazing, choose the extruded rubber gasket geometry that will prevent walk out due to sheet thermal movement and deflection. EPDM and neoprene are common gasket products for the interior glazing side of this application. Setting blocks help to allow for drainage via weep holes and also protect the sheet edge from contact with other liquids that might pool in the sill.



## Wet/Dry glazing

Wet/dry glazing combination uses an extruded rubber and a sealant product. A soft open cell gasket type that breathes allows curing of the sealant cap bead.

Basic glazing is shown in the illustration. Contact your gasket manufacturer for specific instructions for use, as well as preferred tape and sealant products.



# Glazing




## Over-glazing

Over-glazing offers performance enhancements such as energy efficiency and soundproofing. It also offers a design solution where glass alone cannot meet the personal safety requirements or specific threat levels in high risk locations.

### Installation considerations

- » Design a large enough air gap between the glass and TUFFAK sheet to accommodate sheet deflection due to wind or attack load.
- » Wind load is not an issue for interior over-glazing, so a thinner sheet may be an option.
- » The framing must be designed to match the performance of the glazing and appropriate to the threat level of the application
- » Clean sash to be certain it is free of manufacturing contaminants such as cutting oil
- » Ensure sash is smooth and free of burrs
- » Confirm size of sash opening and verify a proper design edge engagement, and expansion/contraction allowances
- » Clean and inspect sheet edges for damage after cutting to size
- » Use a glazing gasket, tape or sealant recommended for polycarbonate with an adequate elongation



### TECH TIP:

To ensure a proper window seal, follow the manufacturer's recommendation for seal compression. As a general rule, 15%-40% impression is adequate for most applications. Over compressing a gasket applies unnecessary stress to the polycarbonate and can lead to product failure.

For detailed information visit: [www.plaskolite.com](http://www.plaskolite.com)

## Selected gaskets, silicone and tape products

### GASKET

**Tremco** - EPDM/ Neoprene:

[http://www.tremcosealants.com/category\\_detail/glazing-solutions/glazing-restoration/design-engineering-group.aspx](http://www.tremcosealants.com/category_detail/glazing-solutions/glazing-restoration/design-engineering-group.aspx)

### SILICONE

**Dow-Corning** - 795/995

<http://www.dowcorning.com/applications/search/default.aspx?R=501EN>

**Momentive** - SCS 2700, SCS1200, SCS 1700, SCS 1800, SCS 2000, SCS 2350, SCS 2800

<http://www.siliconeforbuilding.com>

### TAPE

**Saint-Gobain** - V2100

<http://www.foams.saint-gobain.com/BondingTape/StructuralGlazing/ThermalBond.aspx>

**Tremco** - Polyshim

<http://www.tremcosealants.com/products/polyshim-ii-tape.aspx>

# Glazing




## TUFFAK sheet and Hygard® laminate products

Thickness (inch)	Light Transmission, Typical %	Shading Coefficient	Solar Heat Gain Coefficient	Total Solar	Solar Absorption %	Solar Reflectance %	U-Factor	
							Summer	Winter
0.118	86	0.99	0.87	83	11	6	0.91	1.00
0.177	85	0.99	0.86	82	12	6	0.88	0.96
0.236	84	0.97	0.85	80	14	6	0.85	0.92
0.370	80	0.95	0.83	77	17	6	0.78	0.85
0.480	77	0.93	0.81	75	16	9	0.73	0.79
Tint	70	0.86	0.75	66	27	7	*	*
Tint	50	0.77	0.67	55	38	7	*	*
Tint	18	0.62	0.54	34	60	6	*	*
BR750	89	0.95	0.83	75	19	6	0.64	0.68
BR1000	66	0.88	0.76	65	30	5	0.56	0.60
BR1250	72	0.91	0.79	68	27	5	0.51	0.54
CG375	82	0.94	0.82	76	18	6	0.77	0.84
CG500	79	0.93	0.81	73	21	6	0.72	0.78
CG750	72	0.90	0.79	69	25	6	0.63	0.68
WG 0.75**	71	0.89	0.78	69	23	8	0.62	0.67
WG 1.0**	64	0.86	0.75	64	29	7	0.56	0.60
WG 1.25**	59	0.85	0.74	61	32	7	0.50	0.53
WG 2.0**	48	0.82	0.71	55	39	6	0.39	0.41

\*Thickness dependent

\*\*WG products have limited weathering properties, for more information contact your Plaskolite representative or the Sheet Technical Services Group



## Noise reduction\*

The tables below show sound reduction levels, in decibels, for TUFFAK sheet single and dual glazed systems.

### SINGLE GLAZED

TUFFAK thickness (inch)	Rw (dB)	STC (dB)	OITC (dB)
0.118	24	24	19
0.177	27	27	22
0.236	29	29	24
0.375	33	33	27
0.500	35	34	30

### DUAL GLAZED

Sheet thickness (inch)	Air Space (inch)	TUFFAK thickness (inch)	STC (dB)	OITC (dB)
0.236 PC	0.5	0.236	28	23
0.250 Glass	0.5	0.5	31	26
0.250 Glass	0.5	0.5 laminated	36	28

Distributed by:



Toll Free: 1.800.277.7898  
[www.piedmontplastics.com](http://www.piedmontplastics.com)

These suggestions and data are based on information we believe to be reliable. They are offered in good faith, but without guarantee, as conditions and methods of use are beyond our control. We recommend that the prospective user determine the suitability of our materials and suggestions before adopting them on a commercial scale.

© 2018 **PLASKOLITE, LLC** 082018

TUFFAK® and Hygard® are registered trademarks of Plaskolite LLC

Bayblend® is a registered trademark of Covestro AG

**PLASKOLITE**

400 Nationwide Blvd, Suite 400  
Columbus, OH 43215  
800.254.1707 • Fax: 800.457.3553  
[plaskolite@plaskolite.com](mailto:plaskolite@plaskolite.com)  
[www.plaskolite.com](http://www.plaskolite.com)

BRO002